Adrenaline Diesel

13019 - 151 Street NW Canada, AB T5V 1A7, CA adrenalinediesel@outlook.com (780) 907-1965

Bill To



Invoice:

425

Date:

6/6/2019

Ship To

Service Order		Terms Due Date Authorizer		Authorizer	Customer PO		Unit #
	1219	COD	6/6/2019	BEN			8137-04
Item	Description				Quantity	Rate	Amount
Complaint: REPAIR FOR NO RUN CONDITION Cause: NUMBER THREE LINER BROKEN AND CONNECTING ROD BEARING SPUN.							
Labor	FOUND BEAR RECOMMEND DAMAGE TO L FOR REPLACE	ING SPUN ON NUI ENGINE REPLAC INER BORE WHIC EMENT ENGINE, A	EMENT. INSPECTE H MAKES IT UNUS	NECTING ROD AS WELL. D BLOCK TO FIND ABLE.GAVE ESTIMATE ISSUES WILL BE ADDED	10.0000	\$145.00	\$1,450.00
						Sub Total	\$1,450.00
Complaint: Install newer engine Cause: Previous engine failure (Inspection)							
Labor	Correction: Engine / Botton 6/3/2019	n End / Removed a	nd replaced engine v	vith exchange engine -	35.0000	\$145.00	\$5,075.00
Parts	USED ENGINE	<u> </u>			1.0000	\$24,000.00	\$24,000.00
Parts	15W40 ENGIN	E OIL / L			46.0000	\$5.15	\$236.90
Parts	EXTENDED LI	FE COOLANT			45.0000	\$6.68	\$300.60
Parts	Air filter				1.0000	\$636.31	\$636.31
Parts	LUBE FILTER				1.0000	\$58.62	\$58.62
Parts	Coolant filter				1.0000	\$42.98	\$42.98
Parts	Fuel filter				1.0000	\$33.46	\$33.46
Parts	FLEETGUARD	FUEL FILTER			1.0000	\$68.28	\$68.28
Parts	Rear engine me	ount bushing, bolt a	and nut		2.0000	\$180.98	\$361.96
Parts	Rad mounts				2.0000	\$157.97	\$315.94
Parts	Fuel line from f	uel filter to fuel mar	nfold		1.0000	\$209.97	\$209.97
Parts	Dirty Core for U	JSED ENGINE			-1.0000	\$3,250.00	-\$3,250.00

Item	Description	Quantity	Rate	Amount
Parts	Inherent Core for USED ENGINE	1.0000	\$3,250.00	\$3,250.00
Parts	Fuel line from fuel filter to primer pump	1.0000	\$146.81	\$146.81
Parts	Accesory belt	1.0000	\$28.57	\$28.57
Parts	Serpentine belt	1.0000	\$184.59	\$184.59
Parts	Rear main crankshaft seal	1.0000	\$146.45	\$146.45
Parts	Front main rankshaft seal	1.0000	\$96.71	\$96.71
Parts	GASKET, CONNECTION	1.0000	\$37.75	\$37.75
Parts	O-ring seal for water pump	1.0000	\$14.21	\$14.21
Parts	FREIGHT	1.0000	\$20.80	\$20.80
Parts	INTAKE PLUG/BLOCK PLATE (SMALL - CM2250 & CM 2350)	1.0000	\$118.50	\$118.50
Parts	O-RING FOR INTAKE PLUG / PLATE (SM)	1.0000	\$0.86	\$0.86
Parts	OIL SEAL	1.0000	\$96.71	\$96.71
Parts	OIL DRAIN LINE GASKET, CUMMINS	1.0000	\$6.93	\$6.93
Parts	POWER STEERING GASKET	1.0000	\$7.26	\$7.26
Parts	Freight	1.0000	\$75.00	\$75.00
Parts	FREIGHT	1.0000	\$18.85	\$18.85
Parts	Front engine mount top side bushing and washer	2.0000	\$17.08	\$34.16
Parts	GASKET, INTAKE MANIFOLD	1.0000	\$81.23	\$81.23
Parts	Bolt	2.0000	\$30.32	\$60.64
Parts	Washer	2.0000	\$19.40	\$38.80
Parts	Nut	2.0000	\$11.80	\$23.60
Parts	FREIGHT	1.0000	\$11.38	\$11.38
Parts	OIL PAN GASKET	1.0000	\$328.12	\$328.12
Parts	MANIFOLD STUDS, CUMMINS	4.0000	\$25.19	\$100.76
Parts	Turbo exhaust gasket	1.0000	\$22.72	\$22.72
Parts	TURBO NUT, CUMMINS	4.0000	\$14.74	\$58.96
Parts	SEAL, O-RING	1.0000	\$15.23	\$15.23
Parts	SEALING WASHERS	6.0000	\$8.54	\$51.24
Parts	SEALING WASHER	6.0000	\$7.02	\$42.12
Parts	FREIGHT	1.0000	\$21.13	\$21.13
Parts	SEALING WASHER	2.0000	\$7.30	\$14.60
Parts	WASHER, SEALING	2.0000	\$10.22	\$20.44
Parts	45 deg hose barb to ORB	1.0000	\$13.32	\$13.32
Parts	1/4" SYNFLEX BLACK HOSE / FT	3.0000	\$4.38	\$13.14
Parts	Charge air pipe clamps	2.0000	\$24.86	\$49.72
Parts	2.25" - 3.13" CT CLAMP	2.0000	\$21.63	\$43.26

Item	Description	Quantity	Rate	Amount
Parts	Hard coolant pipe from water pump to tee above eng		\$293.58	\$293.58
Parts	Top AC condenser bushings/mounting brackets		\$83.48	\$166.96
Parts	5/8" hose barb tee	1.0000	\$5.41	\$5.41
Parts	3/4" hose barb tee	1.0000	\$5.90	\$5.90
Parts	FREIGHT	1.0000	\$26.00	\$26.00
Parts	FREIGHT	1.0000	\$24.38	\$24.38
			Sub Total	\$33,906.82
Complaint: REPAIR OIL LEAK #2A AXLE FLANGE Cause: FAILED GASKET (Inspection)				
Labor	Correction: Chassis / Tire & Wheels / NEW GASKET INSTALLED #2A DRIVE FLANGE - 5/31/2019	1.0000	\$145.00	\$145.00
Parts	GASKET	1.0000	\$5.65	\$5.65
			Sub Total	\$150.65
Complaint: REPAIR FOR WORN CLUTCH INPUT SHAFT Cause: Customer request (Inspection)				
Labor	Correction: Transmission / Clutch / REPAIR FOR WORN CLUTCH INPUT SHAFT - 6/4/2019	1.0000	\$145.00	\$145.00
Parts	Pilot bearing for flywheel	1.0000	\$16.97	\$16.97
Parts	Clutch Install Kit	1.0000	\$275,43	\$275.43
Parts	Clutch fork	1.0000	\$308.94	\$308.94
Parts	2 PC CLUTCH BRAKE	1.0000	\$94.49	\$94.49
			Sub Total	\$840.83
Complaint: REPAIR OIL LEAKS ON USED ENGINE Cause: Failed gasket (Inspection)				
Labor	Correction: Engine / Lubrication / Replaced valve cover gasket, tightened up fuel gear pump back plate 6/4/2019	0.0000		\$0.00
Parts	valve cover gasket	1.0000	\$88.85	\$88.85
Parts	FREIGHT	1.0000	\$11.38	\$11.38
			Sub Total	\$100.23

Unit: 8137-04 VIN: 3HSCXAPR9FN040376

2015 International Lonestar Chassis: 440,719 Kilometers

Labor \$6,815.00

Parts \$29,633.53

Shop Supplies \$300.00

Pre Tax Total \$36,748.53

GST (5.0000% of \$36,748.53) \$1,837.43

Total \$38,585.96

Payments & Credits \$0.00

Balance Due \$38,585.96