TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver		Date Mar 25/19		Date of HRS	Mechanic	HRS
					Closing Date Mar 25		Mar 25	Le Ry	7
			Unit Hours 6973	Odometer					
			Unit Number 136	Year 2006	Make Sterling	Model Actima			
			Serial No. 51510			Written By Le Ry			
			Change Compressor						
	TOTAL PARTS								

136

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver		Date Mar 13/19		Date of HRS	Mechanic	HRS
1	B7600				Closing Date Mar			[illegible]	
1	RS2863		Unit Hours 6953	Odometer					
20	H 0.1		Unit Number 136	Year 06	Make Sterling	Model M8500			
1	BT287-10		Serial No. 51510			Written By [illegible]			
1	04-20002-000	275 04	Lenning						
1	010028-006	14 82	Repair muffler Clamp.						
			Replace exhaust Pipe & Clamp						
	GST	14.49							
	TOTAL PARTS	304 35							

136
[illegible]

Alberta TRANSPORTATION

COMMERCIAL VEHICLE RECORD OF INSPECTION

136

(Please Print)

Registered Owner's Name Twin City

Phone _____ Fax _____

Vehicle Make Sterling Vehicle Model _____ Year 2006

Odometer 204041.0 km Unit# 136 License Plate No. 32-M117 GVWR or Bus Cap _____

Vehicle Identification number 2FZHCHDC76AV51510

RECORD MEASUREMENTS

	LEFT	FRONT	RIGHT	
	62	DRUMS/ROTORS	72	
m.m. 16	5/8	LININGS/PADS	5/8	17 m.m.
PSI 105	1/2	PUSH ROD TRAVEL	1/2	105 PSI
		~~CAM ROTATION~~		
	54	DRUMS/ROTORS	60	
m.m. 15 / 12	Fail	LININGS/PADS	Fail	16 / 16 m.m.
PSI 105 / 105	1/2	PUSH ROD TRAVEL	1 1/2	105 / 105 PSI
		~~CAM ROTATION~~		
	55	DRUMS/ROTORS	55	
m.m. 18 / 17	7/16	LININGS/PADS	7/16	9 / 12 m.m.
PSI 105 / 105	1 1/8	PUSH ROD TRAVEL	3/4	105 / 105 PSI
		~~CAM ROTATION~~		
		DRUMS/ROTORS		
m.m.		LININGS/PADS		m.m.
PSI		PUSH ROD TRAVEL		PSI
		CAM ROTATION		

WHEELS TORQUE CHECKED ☑

{ Identify by location if Wheels Removed at time of Inspection }

Mechanic's Comments

LF & LR marker lights not working on gravel box, Muffler clamp is broken, Air compressor slow for build up air, LR air bag pedestal broken, RF Rivet Bushing Both FO Brake Fail

14812 — Inspection Station Number

2019 03 01 — Inspection Date (YY MM DAY)

Time AM/PM

CVIP Certificate (if) Issued ☐ Yes ☒ No

JOC — Name of Inspection Mechanic (Print)

Signature of Inspection Mechanic

A2959 — Mechanic Number

Vehicle received without Repairs To Rejected Items YES _____

Signature of Vehicle Owner or Representative

Title

LRD Shocks, Torq arm's to Be Monitored

KAL TIRE
14720 YELLOWHEAD TRAIL NW
EDMONTON, AB
3C5
Phone: 780-451-5417
Fax: 780-451-3311

KALTIRE

WORK ORDER
Work Order #: 087050257L
Date: Mar 06 2019
Page: 1
Team Member: SDARICHUK

Customer Waiting? No
REQUIRED: Mar 06 2019 12:30 PM

TWIN CITY EXCAVATING INC.
25846 115 AVENUE
ACHESON, AB
T7X 6C5

Take-off tires? Return to Customer
Keys?
TPMS? No

TWIN CITY EXCAVATING INC.
25846 115 AVENUE
ACHESON, AB
T7X 6C5
Phone: (780) 447-4737

Account: 6134006

Vehicle: 2006 STERLING STERLING

PO #: 136

Year: *2006
Make: *STERLING
Model: *STERLING
Unit: 136
Lic #: *32M117
Prov: *AB
Vin: *2FZHCHDC76AV51510
Mi/KM: 204062

Team Member	Qty	Product Code	Description	Unit
	2	509030	HEAVY DUTY SUSPENSION PARTS	TAG
OTH 046-1307-00 SPRING				
OTH 046-1307-00 SPRING				
	1	509030	HEAVY DUTY SUSPENSION PARTS	TAG
OTH 046-1309-00 SPRING				
	1	509030	HEAVY DUTY SUSPENSION PARTS	TAG
AG1236569050 OTH 046-1309-00 SPRING				
	3	FL40	FREIGHTLINER WEAR PADS	PCS
	3	FL41	FREIGHTLINER WEAR PADS	PCS
	8	7836	7/8 X 36 U-BOLT ROD	PCS
	6.00	FEHT	REPLACE 4 REAR AIR LINER SPRINGS	HR
	1	ATC	TOE SET / CHECK ALIGNMENT	EA
		FRONT PIVOT BUSHINGS AND REAR ATC		
	2	ATCA	CASTER ADJUST [PARTS EXTRA]	EA
	1	ATUBOLT	***** RETORQUE U-BOLTS AFTER 500KM *****	EA
	1	AL1073	4" X 2 DEGREE AXLE SHIM (6)	PCS
	1	ATCSW	CENTER STEERING WHEEL	EA
	1	ATA1	ADJUST FRONT/REAR DRIVE AXLES	EA
	1	SHOP	SHOP SUPPLIES	EA
		6 THRUST SHIMS @ 8.00 EACH 8 GRADE 8 BOLTS @ 10.00 EACH		

Additional Mandatory Items

DRIVERS NAME: CURTIS

KAL TIRE
14720 YELLOWHEAD TRAIL NW
EDMONTON, AB
[illegible] 3C5
Phone: 780-451-5417
Fax: 780-451-3311

KALTIRE®

WORK ORDER
Work Order #: 087050257L
Date: Mar 06 2019
Page: 2
Team Member: SDARICHUK

I HEREBY AUTHORIZE AND REQUEST THE ABOVE WORK BE DONE AND NECESSARY MATERIALS SUPPLIED. I RELEASE KAL TIRE AND ITS EMPLOYEES FROM ALL CLAIMS AGAINST THEM RELATING TO THE ABOVE DESCRIBED VEHICLE AND ANY CONTENTS WHILE THE VEHICLE IS IN THE POSSESSION OF KAL TIRE.

Signed X

Printed: Mar 07 2019 10:25
Driver: CURTIS
Phone: 7802360898

Team Member Initials

FLEET BRAKE PARTS & SERVICE

FLEET BRAKE
Truck - Trailer Parts and Service
www.fleetbrake.com

18410-118A AVE NW
EDMONTON AB T5S 2M3
780-455-0559

INVOICE DATE	
03/06/2019 09:14AM	
INVOICE NO.	PAGE
2290650024	1
CUSTOMER NO.	BRANCH
03103	* 2*

SOLD TO:
TWIN CITY EXCAVATING
INC
25846 115 AVE
ACHESON AB T7X 6C5

SHIP TO:
TWIN CITY EXCAVATING
INC
25846 115 AVE
ACHESON AB T7X 6C5

CUSTOMER P.O.	REFERENCE NO.	GST# R101819472		
UNIT 136	990962	(780) 447-4737	82	071/82 000

		PRICE/PER	EXTENSION
	TERMS: (00) N30		
	TO BE DELIVERED		
2	ERN KITFR4707-501FFASHOE KIT 2 NEW Q+ SHOES/HDW	64.20EA	128.40
2	DUM 100240B BRAKE DRUM 16.5 X 7	89.95EA*	179.90
	DEL IN AM		
	*** SUB-TOTAL:		308.30
	*** PST/PST TXBL -PROVINCE:AB		N/C
	*** GST - 101819472		15.42

RESTOCK CHARGES MAY APPLY ON RETURNED PRODUCT

I, THE UNDERSIGNED OWNER OR DULY AUTHORIZED REPRESENTATIVE, AUTHORIZE THE REPAIR AND SERVICE WORK LISTED ABOVE TO BE DONE, ALONG WITH MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT FLEET BRAKE PARTS & SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. FURTHER, I ACKNOWLEDGE FULL RESPONSIBILITY FOR ANY DAMAGE RESULTING FROM INADEQUATE COLD WEATHER PROTECTION. WHEEL MANUFACTURES RECOMMENDED CHECKING THE TORQUE IN FASTENERS ON PASSENGER CARS/LIGHT TRUCKS AND TRAILERS AT 30-50 KM AND MEDIUM/HEAVY TRUCKS AND TRAILERS AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REQUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAR DAYS OR 1000 KM IF THE U-BOLTS HAVE BEEN REPLACED. FLEET BRAKE FREELY GUARANTEES THAT ALL WORK PERFORMED WILL BE FREE OF DEFECTS IN MATERIAL OR WORKMANSHIP, UNDER NORMAL USE AND SERVICE, FOR A PERIOD OF NINETY (90) DAYS OR FOUR THOUSAND (4000) MILES OR SIXTY-FOUR HUNDRED (6400) KM, WHICHEVER OCCURS FIRST, FROM THE DATE OF COMPLETION OF SUCH WORK. SEE OUR FULL WARRANTY POLICY AT WWW.FLEETBRAKE.COM/SERVICE. PAYMENT TO BE NET 30 DAYS FOLLOWING DATE OF INVOICE UNLESS OTHERWISE SHOWN. A SERVICE CHARGE OF 2% PER MONTH (24% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE VEHICLE DESCRIBED ON THIS ORDER TO SECURE THE FULL AMOUNT OF SERVICES THERETO.

WORK AUTHORIZED AND PAYMENT GUARANTEED BY ▶ _____

FREIGHT	SUBTOTAL	TAX STATUS/STATE	SALES TAX	PLEASE PAY
	308.30			323.72

TERMS

PLEASE REMIT TO:
C/O C25032
PO Box 2532
Station M
CALGARY, AB
T2P 5P9

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver		Date Mon 6/19		Date of HRS	Mechanic	HRS
1	10028-6	STOCK			Closing Date Mon 6/19		MAR6	Lefty	4
	EXHAUST CLAMP		Unit Hours 6932	Odometer 204847					
			Unit Number 136	Year 06	Make Sterling	Model Acterra			
2	KITER4707	12840	Serial No. 51510			Written By Lefty			
2	DUM100240B	17990							
1	N320197581	7965	Change exhaust Clamp.						
			Change L/R Air Line						
			Change 2ND Axle Drums & shoes						
			Replace replaced 4 leaf springs & U Bolts						
	TOTAL PARTS								

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price
1	4C4H-19A706-AA	34.75
	HEATER RESISTOR	
	TOTAL PARTS	

Driver

Date NOV 15/18

Closing Date NOV 15/18

Unit Hours 6540 Odometer 191748

Unit Number 136 Year 06 Make STERLING Model ACTERRA

Serial No. V51510 Written By BLL

- CHECKED OUT HEATER OPERATION - FAN INTERMITTANTLY KICKING IN + OUT, ONLY WORKS ON HIGH SPEED
- REPLACED HEATER RESISTOR

Date of HRS	Mechanic	HRS
NOV 15	BLL	1.0

- CHECKED HEATER DOOR OPERATION - OK. CHECKED HEATER MODE MODULE - FOUND MODULE SWITCH CUTS IN + OUT RANDOMLY. NEEDS NEW MODULE - 360.00! MODULE REPLACED.

Date of HRS	Mechanic	HRS
NOV 15	BLL	2.0

136 BLL

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price						Date of HRS	Mechanic	HRS
			Driver BRIAN		Date JAN 4/19					
1	4C4H-19A706-AA				Closing Date JAN 4/19					
	RESISTOR BLOCK		Unit Hours 6725	Odometer 197330						
1	A22-57400-004	378.74	Unit Number 136	Year 06	Make STERLING	Model ACTERRA				
	CONTROL MODULE		Serial No. 51510			Written By BWB				
	(HEATER)		- REPLACED HEATER CONTROL MODULE					JAN 4	BB	1.0
			- REPLACED HEATER MOTOR RESISTOR							
			(3RD TIME), CHECKED HEATER MOTOR,							
			CHECKED, CLEANED + LUBED HEATOR							
			MOTOR WIRING CONNECTOR.					JAN 4	BB	1.0
	TOTAL PARTS	$378.74					136 BB			

FINNING CAT

FINNING CANADA LTD. - Fluid Analysis Laboratory,10910-170th Street, Edmonton, AB, T5S 1H6, CANADA
PHONE: 1-888 FINNING (346-6464)
Email: oilsupport@finning.com Web: www.finning.com

CONTACT INFORMATION

BILL BECK
TWIN CITY EXCAVATING INC
108 26230 TWP RD 531A
ACHESON, AB
CA T7X 5A4
PHONE: 7804474737
FAX: 7804825426
Email: BILL@TWINCITYEX.COM

EQUIPMENT

CUSTOMER EQUIP NUM : 136
SERIAL NUMBER : 76AV51510
MODEL : M8500_STERLING
MANUFACTURER : STERLING
COMPANY NAME : TWIN CITY EXCAVATING INC
JOB SITE :
AREA:
REGION:

SAMPLE INFORMATION

COMPARTMENT NAME : ENGINE
COMP SERIAL NUM :
COMPARTMENT MODEL :
LABEL#: 005093674
SHOP JOB NUM :
SAMPLE TYPE: OIL
SAMPLE SHIP TIME (days) : 14
SAMPLE LOCATION :

Interp By: Peter Leggo

No Action Required

DIRT AND WEAR METALS APPEAR TO BE AT ACCEPTABLE LEVELS. OTHER READINGS APPEAR TO BE NORMAL. RESAMPLE AT THE NEXT SERVICE INTERVAL.

LAB #
N030-48311-0115
PROCESS DATE 07-Nov-18

WEAR/CONTAMINATION - ADDITIVES/FORMULATION

SAMPLE DATE	SAMPLE ID	METER (HR)	METER ON FLUID	FLUID CHANGE	FILTER CHANGE	Na	K	Si	Al	Fe	Cr	Pb	Cu	Sn	Ni	Ag	Ti	V	Zn	Ca	Mg	Ba	B	Mo	P
24-Oct-18	N030-48311-0115	6472	580	Y	Y	2	2	3	2	19	1	2	1	0	0	0	0	0	1229	1182	909	0	22	57	999
31-May-18	N030-48180-0136	5901	500	Y	Y	1	4	3	3	22	1	2	1	0	0	0	0	0	1236	1107	757	0	108	70	1043
30-Aug-17	N030-47248-0333	5413	906	Y	Y	2	5	3	3	17	1	3	1	0	0	0	0	0	1197	1464	419	0	255	85	1032
02-Jun-17	N030-47157-0113	4950	450	U		1	3	3	2	15	1	1	0	0	0	0	0	0	1017	1216	357	0	37	72	907

OIL FORMULATION - OIL CONDITION - OIL CONTAMINATION

SAMPLE DATE	SAMPLE ID	METER (HR)	METER ON FLUID	FLUID BRAND	FLUID TYPE	FLUID WEIGHT	FLUID CHANGE	FILTER CHANGE	V100	V40	VI	ST	OXI	SUL	NIT	A	F	PFC
24-Oct-18	N030-48311-0115	6472	580	CHEVRON	UNKNOWN	15W-40	Y	Y	12.0	85.7	133	16	19	22	10	N	N	0.49
31-May-18	N030-48180-0136	5901	500	CHEVRON	UNKNOWN	5W-40	Y	Y	12.1	81.0	145	17	21	22	11	N	N	0.49
30-Aug-17	N030-47248-0333	5413	906	CHEVRON	DELO 400	15W-40	Y	Y	13.1	102.1	125	15	21	22	10	N	N	
02-Jun-17	N030-47157-0113	4950	450	CHEVRON	DELO 400	15W-40	U		13.0	93.6	137	10	19	21	9	N	N	

OIL CLEANLINESS

SAMPLE DATE	SAMPLE ID	FLUID CHANGE	FILTER CHANGE	W
24-Oct-18	N030-48311-0115	Y	Y	N
31-May-18	N030-48180-0136	Y	Y	N
30-Aug-17	N030-47248-0333	Y	Y	N
02-Jun-17	N030-47157-0113	U		N

BBL, 136

A = Antifreeze, Ag = Silver, Al = Aluminum, B = Boron, Ba = Barium, Ca = Calcium, Cr = Chromium, Cu = Copper, F = Fuel, Fe = Iron, K = Potassium, Mg = Magnesium, Mo = Molybdenum, NIT = Nitration, Na = Sodium, Ni = Nickel, OXI = Oxidation, P = Phosphorus, PFC = Percent Fuel Content, Pb = Lead, ST = Soot, SUL = Sulfation, Si = Silicon, Sn = Tin, Ti = Titanium, V = Vanadium, V100 = Viscosity@100C, V40 = Viscosity@40C, VI = Viscosity Index, W = Water, Zn = Zinc

Notice: This analysis is intended as an aid in predicting mechanical wear. No guarantee, expressed or implied, is made against failure of this piece of equipment or a component thereof.

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver		Date OCT 25/18		Date of HRS	Mechanic	HRS
1	4C4H19A706AA RESISTOR	31.45			Closing Date OCT 30/18				
1	YFRH18A559AB	30.00	Unit Hours 6495	Odometer 190181					
	DOOR		Unit Number 136	Year 06	Make STERLING	Model ACTERRA			
			Serial No. 51510			Written By BLL			
			- STRAIGHTENED BOX LATCH ROD,						
			ADJUSTED LATCHES				OCT 25	BLL	3.0
			- REPLACED HEATER RESISTOR BLOCK				OCT 30	BLL	.5
			- REPLACED HEATER VENT DOOR				OCT 31	BLL	1.5
			- REPAIRED RH TARP ROD - WELDED						
			NEW BOLT INTO TARP, REATTACHED						
			RH TARP ARM + SPRING				OCT 31	BLL	1.5
	TOTAL PARTS								

Western
TRUCK & TRAILER

FUSO

18353-118 Avenue, Edmonton, AB T5S 1M8
Phone: (780) 481-7400
Fax: (780) 481-7725
Website: www.westernsterling.com

OK TIRE
Honestly driven.

ALL CLAIMS AND RETURNED GOODS MUST BE ACCOMPANIED BY THIS INVOICE. NO RETURN ON ELECTRICAL OR SPECIAL ORDER PARTS. NO RETURNS AFTER 30 DAYS. 20% RESTOCKING CHARGE ON ALL RETURNED PARTS
TERMS: NET 30 DAYS, INTEREST OF 2% PER MONTH (24% PER ANNUM) ON ALL OVERDUE ACCOUNTS.
GST NUMBER: 867068173RT

PARTS & SERVICE HOURS: MON. - FRI. 7:30 AM - 9:00 PM

DATE ENTERED	YOUR ORDER NO.	DATE SHIPPED	INVOICE DATE	INVOICE NUMBER
30 OCT 18	136	30 OCT 18	30 OCT 18	265494P

SOLD TO

ACCOUNT NO. 3519

TWIN CITY EXCAVATING INC
25846 - 115 AVE
ACHESON, AB T7X 6C5

SHIP TO

PAGE 1 OF 1

SHIP VIA	SLSM.	B/L NO.	TERMS	F.O.B. POINT
PU	1415			EDMONTON, AB

QUANTITY ORD.	SHIP	B.O.	PART NO.	DESCRIPTION	LIST	NET	AMOUNT
1	1	0	4C4H*19A706*AA C09C06	RESISTOR	41.78	31.45	31.45
1	1	0	YFRH*18A559*AB C09C07	DOOR - V	35.99	30.00	30.00

ASK FOR OUR CURRENT H.TRK FLYER
SPECIALS ON BRAKE KITS, STEMCO SEALS,
U-JOINTS, BATTERIES, FILTERS
PLUS MANY MORE IN STORE SPECIALS
PARTS DIRECT PH.

CUSTOMER'S SIGNATURE
X

PARTS	61.45
SUBLET	
FREIGHT	0.00
SALES TAX	3.07
TOTAL	$64.52

AlliedSignal Bendix
STERLING TRUCKS
DANA SPICER
GUNITE
Rockwell

Copyright 2014 CDK Global, LLC PARTS INVOICE 1UP - PI3C1 - IMAGING
x1pi1.100_1

CUSTOMER COPY

KIRK'S TIRECRAFT

Kirk's Tire Edmonton
16806 - 118 Avenue Edmonton AB T5V 1M8
Phone: (780)488-9911 Fax: (780)488-9904

INVOICE E041010 (Copy)

SOLD TO: TWICIT
TWIN CITY EXCAVATING INC.
25846 115AVE
ACHESON
T7X 6C5 AB
TEL: 780 4474737 FAX: 780 4825426

CONTACT:

DATE: 18 Oct 26

INVOICE TO:

PAGE: 1

YEAR	MAKE	MODEL		ENGINE
PLATE NO	VIN	ODOMETER	UNIT NO.	WRITTEN BY
TIME IN	PROMISED	TERMS	GST#	P.O.	TAG
2:53 PM		30 DAYS	189877	860585215	136	UNIT#136	DB

QTY	ITEM/DESCRIPTION	SIZE	TAX	RETAIL	%	NET	EXT.PRICE
1	AHS AFTER HOURS SERVICE CALL 18 Oct 25		G	175.00		175.00	175.00
2	55458 BFGOODRICH ST230 L TTH	315/80R22.5	G	874.00	20	699.20	1398.40
2	TIRE RECYCLING FEE H. TRUCK		G	9.00	0	9.00	18.00
2	CMTP CHANGEOVER MED TRK WITH PURCHASE 18 Oct 25		G	35.00		35.00	70.00
2	BMT BALANCE MEDIUM TRUCK 18 Oct 25		G	45.00		45.00	90.00
	WO#660275						
	WHEELS MUST BE RE-TORQUED WITHIN 100 KMS						

136

COPY

MICHELIN BFGoodrich UNIROYAL TOYO TIRES National

HBRIDGE 827-5985 | CAROSTON 403-653-4914 | TABER 403-223-3441 | BROOKS 403-362-6647 | REDCLIFF 403-548-3941 | CALGARY 403-243-8811 | RED DEER 403-347-1004 | EDMONTON 780-488-9911

Name: _____ Signature: _____

With the above signature I agree to the terms below and acknowledge indebtedness for the total amount owing as shown hereon, or in the amount of any cheque or credit card given in payment and later dishonored. A SERVICE CHARGE OF 26.86% PER ANNUM (2% PER MONTH) WILL BE CHARGED ON PAST DUE ACCOUNTS.

PARTS:	1398.40
LABOUR:	335.00
OTHER:	18.00
SUB-TOTAL:	1751.40
GST:	87.57
PST:	N/C
TOTAL:	**1838.97**

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver	Date October 24/2018	Date of HRS	Mechanic	HRS
1	B7600 oil filter	STK		Closing Date	Oct. 24	Daniel	3.0
26L	15W-40	STK	Unit Hours 6472 hrs.	Odometer	Oct. 24	Curtis	1.0
1	BF7632 fuel filter	STK	Unit Number 136	Year 2006 Make Sterling Model M8500 Acterra			
1	RS2863 air	STK	Serial No. AV5151 0	Written By Daniel			
1	PA5337 cab air	STK	- Service				
			-replace oil and oil filter				
			-replace fuel filter				
			-replace air and cab air				
			- grease: drive line = 30 pumps, Steering = 15 pumps, bucket 30				
	TOTAL PARTS						

136 bf

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver	Date OCT 1/18	Date of HRS	Mechanic	HRS
1	F7HZ-18476-AA	108.69		Closing Date OCT 2/18			
	HEATER CORE		Unit Hours / Odometer 186183				
1	ABP/N32-019781		Unit Number 136 / Year 06 / Make STERLING / Model ACTERRA				
	C11602	104.95	Serial No. V51510	Written By BLL			
	AIR BAG		- REPLACED HEATER CORE, TOPPED UP				
1	NEL 89924A	45.47	A/FREEZE + TESTED - OK.		OCT2	BLL	2.5
	EXHAUST ELBOW		- REPLACED RR AIR BAG		OCT2	BLL	1.5
			- CUT OFF ROTTEN AREA OF EXHAUST				
			STACK, INSTALLED 90° EXHAUST ELBOW				
			AND NEW FLEX PIPE + CLAMPS		OCT2	BLL	1.5
			- WELDED CRACKS, FILLED HOLES IN				
			BOX UNDER TAILGATE		OCT2	BLL	2.0
	TOTAL PARTS						7½

259.11

136

BL

Kirk's Tire Edmonton
16806 - 118 Avenue Edmonton AB T5V 1M8
Phone: (780)488-9911 Fax: (780)488-9904

INVOICE E040614 (Copy)

CONTACT:

DATE: 18 Sep 26

SOLD TO: TWICIT
TWIN CITY EXCAVATING INC.
25846 115AVE
ACHESON AB
T7X 6C5
TEL: 780 4474737 FAX: 780 4825426

INVOICE TO:

PAGE: 1

YEAR	MAKE	MODEL	ENGINE

PLATE NO	VIN	ODOMETER	UNIT NO.	WRITTEN BY
		0	136	CW

TIME IN	PROMISED	TERMS	GST#	P.O.	TAG
1:08 PM		30 DAYS	860585215	UNIT#136	

QTY	ITEM/DESCRIPTION	SIZE	TAX	RETAIL	%	NET	EXT.PRICE
1	**AHS AFTER HOURS SERVICE CALL 18 Sep 26** 127ST 153AVE		G	175.00		175.00	175.00
1	U225 KIRKS 11R22.5 USED BRIDGESTONE		G	175.00	0	175.00	175.00
1	**CMTP CHANGEOVER MED TRK WITH PURCHASE 18 Sep 26**		G	35.00		35.00	35.00
1	BOOT RADIAL BOOT		G	10.00	0	10.00	10.00

.
FIXED A FLAT AND TIRE BLEW UP WHILE AIRING UP
RIGHT REAR OUTSIDE DONE ON UNIT
WO#560233

WHEELS MUST BE RE-TORQUED WITHIN 100 KMS

136
BR

COPY

WARNING: PLEASE ENSURE LUG NUTS ARE TORQUED WITHIN 100 KMS

MICHELIN BFGoodrich UNIROYAL TOYO TIRES National

HBRIDGE	CARDSTON	TABER	BROOKS	REDCLIFF	CALGARY	RED DEER	EDMONTON
327-5985	403-653-4914	403-223-3441	403-362-6847	403-548-3941	403-243-8811	403-347-1004	780-488-9911

PARTS:	185.00
LABOUR:	210.00
OTHER:	N/C
SUB-TOTAL:	395.00
GST:	19.75
PST:	N/C
TOTAL:	**414.75**

Name:_____ Signature:_____

With the above signature I agree to the terms below and acknowledge indebtedness for the total amount owing as shown hereon, or in the amount of any cheque or credit card given in payment and later dishonored. A SERVICE CHARGE OF 26.86% PER ANNUM (2% PER MONTH) WILL BE CHARGED ON PAST DUE ACCOUNTS.

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver		Date JUL 24/18		Date of HRS	Mechanic	HRS
10	WHEEL STUD	$51.40			Closing Date JUL 24/18				
10	WHEEL NUT	$45.80	Unit Hours 6117	Odometer 177421					
1	30055		Unit Number 136	Year 06	Make STERLING	Model ACTERRA			
	50A BREAKER	$11.30	Serial No. 51570			Written By BILL			
1	75712-04		-REMOVED RR TANDEM WHEELS						
	TARP SWITCH	$71.32	+ BRAKE DRUM, REPLACED ALL						
4	NEW RIM'S	$616.88	WHEEL STUDS + NUTS (STUDS						
			DAMAGED + BROKEN).				JUL 24	BILL	2.0
			- FOUR RS. WHEELS WERE REPLACED				JUL 24	KIRK	
			-REPLACED TARP SWITCH + BATTERY						
			BOX BREAKER				JUL 24	BILL	2.0
			- STRAIGHTENED REAR TARP ROD				JUL 24	BILL	1.0
		$796.70							
	TOTAL PARTS								

BILL
136

KIRK'S TIRECRAFT

Kirk's Tire Edmonton
16806 - 118 Avenue Edmonton AB T5V 1M8
Phone: (780)488-9911 Fax: (780)488-9904

INVOICE E039836 (Copy)

CONTACT:

DATE: 18 Jul 24

SOLD TO: TWICIT
TWIN CITY EXCAVATING INC.
25846 115AVE
ACHESON AB
T7X 6C5
TEL: 780 4474737 FAX: 780 4825426

INVOICE TO:

PAGE: 1

YEAR	MAKE	MODEL	ENGINE

PLATE NO	VIN	ODOMETER	UNIT NO.	WRITTEN BY
		0	136	CP

TIME IN	PROMISED	TERMS	GST#	P.O.	TAG
4:00 PM		30 DAYS	860585215	UNIT#136	

QTY	ITEM/DESCRIPTION	SIZE	TAX	RETAIL	%	NET	EXT.PRICE
1	**SC SERVICE CALL 18 Jul 24**						
2	WU225		G	95.00		47.50	47.50
	KIRKS USED 22.5 WHEELS	22.5	G	80.00	0	80.00	160.00
2	22408U						
	EXTREME WHEEL UNIMOUNT WHITE STEEL WHEEL	22.5X8.25	G	172.00	30.23	120.00	240.00
4	**CMTP CHANGEOVER MED TRK WITH PURCHASE 18 Jul 24**		G	35.00		35.00	140.00
	.						
	RIGHT FRONT SET AND RIGHT REAR SET						
	WHEELS MUST BE RE-TORQUED WITHIN 100 KMS						

BRL

COPY

MICHELIN BFGoodrich UNIROYAL TOYO TIRES National

LETHBRIDGE	CARDSTON	TABER	BROOKS	REDCLIFF	CALGARY	RED DEER	EDMONTON
403-327-5985	403-653-4914	403-223-3441	403-362-6647	403-548-3941	403-243-8811	403-347-1004	780-488-9911

Name: _____ Signature: _____

With the above signature I agree to the terms below and acknowledge indebtedness for the total amount owing as shown hereon, or in the amount of any cheque or credit card given in payment and later dishonored. A SERVICE CHARGE OF 26.86% PER ANNUM (2% PER MONTH) WILL BE CHARGED ON PAST DUE ACCOUNTS.

PARTS:	400.00
LABOUR:	187.50
OTHER:	N/C
SUB-TOTAL:	587.50
GST:	29.38
PST:	N/C
TOTAL:	**616.88**

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver		Date JUL 3/18		Date of HRS	Mechanic	HRS
1	7X17 TARP	STOCK			Closing Date JUL 3/18				
			Unit Hours 6007	Odometer 174172					
			Unit Number 136	Year 06	Make STERLING	Model M8500			
			Serial No. 51510			Written By BILL			
			- REPLACED TARP				JUL 3	BILL	1.0
					136 BRL				
	TOTAL PARTS								

TWINCITY EXCAVATING INC.

SHOP WORK ORDER

Qty.	Part No. & Discription	price	Driver		Date May 31/18		Date of HRS	Mechanic	HRS
1	13700 oil				Closing Date "		May 31/18	Curtis	2
1	~~Bf~~ fuel filter		Unit Hours 5901	Odometer 171618					
1	air filter		Unit Number 136	Year 06	Make Sterling	Model Bucterm			
1	cabin air		Serial No. 6AU51510			Written By Curtis			
			+ Service						
			- oil, oil filter, oil sample						
			- fuel filter						
			- air filter						
			- grease						
			- cabin air filter						
	TOTAL PARTS								

136
AM