Repair Order Detail - Internal Copy

RO Number: 721527

RO Status: CLOSED

Customer: H & B OILFIELD SE Phone(s): Contact: (403)998-90 Vehicle: 1FUJA6CK38LZ79887	022 Main: (403)998-9022	Click to View Cust Copy Cell: 6
Mileage: 827,146 Service advisor: 741 Tag number: T4	Payment type: 6C Promised time: 05:00 PM Promised date: 11/11/2016	Waiter: No Estimate: 0.00 Customer Comments: No
A SERVICE CALL FOR U M-39 CPE Tech(s): 882, 622, 668	ROSEDALE SHOP, R&I TOP END, TIME FRONT GEAR TRAIN	R REPLACED INJECTOR 10.00 1,440.00
Pts: 0.00 Lbr: Story: 827146 SET THE VA EXH AND 0.008" TO 0.010" II ENOUGH TO GET HERE. ST AND REMOVED THE EXHAU EXCESSIVE FUEL ENTERIN RED DEER FOR INFO. REM ENGINE. FOUND THE CAM THE GEAR. RE-MOVED THE ACTUATORS, CAM SHAFT O EVERYTHING BACK TOGET	1,440.00 Other: LVES THIS MORNING FROM 0.020" NT. SET INJECTORS. TRUCK RAN L TILL HAS ISSUES. BLOCKED THE E JST MANIFOLD, #2,3,4 CYLINDERS IG THE CYLINDER. CALLED FREIGI OVED THE CAM COVER AND PINN SHAFT TO BE ADVANCED BY ONE E VALVE COVER, JAKE HEADS, VAL CAPS. TURNED THE CAM BACK A T THER, RESET THE VALVES, HOOKE ET THE CODES. TEST DROVE. OK.	TO 0.022 ONG GR VALVE, HAVE HTLINER ED THE TOOTH ON VE OOTH, PUT ED UP THE
B** CLUTCH, REPAIR OR M-69-11 CP		10.00 1,390.00
Tech(s): 668 FARPC1462532 SB200	4 UNION CO 1 BABCOCK 2.00" CLU	36.96 TCH 31.41
C20892525 FARPC146210 FAR146810D 49X10 FAR103A FARGWR312	BRAKE 1 INSTALLA 1 UNION CO 1 AB CONN 1 ADAPTER 1 COUPLER 1 GREASE W	1,213.07 13.84 7.26 14.60 1.26 8.11
ZBJD838000 FARPC622 FRT	3 TUBING-SPLIT FLEX 4 UNION CO 1 FREIGHT CHARGE E ORDER	3/8 0.96 33.12
M-69-11 CP Tech(s): 668	REAR MAIN SEALL R&R	1.00 139.00
DDE23519651 M-69-11 CP Tech(s): 668	1 REAR MAIN SEAL INSTALL SUITCASE KIT	126.292.00278.00
FULK2468 SUBL CP Pts: 1,793.76 Lbr: Page 1, Created: 02/12/2020 11:26:46 AM	1 KIT MACHINE THE FLYWHEEL 1,807.00 Other: 22	284.45 225.00 5.00 Total Line B: 3,825.76

Repair Order Detail - Internal Copy

RO Number: 721527 RO Status: CL			OSED			
Customer: H & B Phone(s): Contac Vehicle: 1FUJA60	t: (403)998-9	022 Main: (403)99		HB156	Click to View Cust Co Cell:	ру
Mileage: 827,146 Service advisor: 7 Tag number: T4	'41	Payment type Promised tim Promised da	e: 05:00		Waiter: No Estimate: 0.00 Customer Comments	: No
Story: 827146 PULLED THE TRANY DOWN AFTER REMOVING ONE AIR TANK. PUT A NEW SEAL IN THE MOTOR AND BOLTED UP THE MACHINED FLY WHEEL. NEXT THE TRANY GOT A SUIT CASE KIT INSTALLED. HAD TO REMOVE THE CLUTCH LINKAGE TO FREE IT UP. CHECKED THE OIL LEVEL AND WENT FOR A ROAD TEST.						
C** PERFOR M-83		CIAL VEHICLE INSP PERFORM COMME VEHICLE INSPECT	RCIAL		.40	349.00
Tech(s):						
M-69-4	CP	BRAKES, AIR/HYDRAULIC, R	EPAIR	2	.00	278.00
Tech(s):						
FLTP4707	QP23K	1 KT SH BRAK	IOE,FLE E SHOE			93.72
FLTP4707	QP23K	-1 CORE	RETUR	RN		-36.80
ZAJ32329	51	2 CHAN	1BER-BF			332.56
	9.48 Lbr:				0 Total Line C:	1,016.48
Story: 827146 REPLACING AND INSPECTING BRAKES, ON AXLE #3						
RIGHT, REPLACING AXLE #2, #3 LEFT BRAKE POTS , ADJUST ALL						
BRAKES AND TORQUE ALL WHEELS.						
~~~~~~~~~~	~~~~~~~		~~~~~~		~~~~~~	~~~

Customer Pay	
Labor	3,874.00
Parts	2,183.24
Lube	0.00
Sublet	225.00
Miscellaneous/Shop Charge	250.00
Deductible	0.00
Total Charges	6,532.24
Less Insurance/Adjustment	0.00
Sales Tax	326.61
Total	6,858.85