

Repair Order Detail - Internal Copy

RO Number: 721483

RO Status: CLOSED

Customer: H & B OILFIELD SERVICES

[Click to View Cust Copy](#)

Phone(s): Contact: (403)998-9022

Main: (403)998-9022

Cell:

Vehicle: 1FUJA6CK38LZ79887

2008 COLUM

HB156

Mileage: 827,146

Payment type: 6C

Waiter: No

Service advisor: 622

Promised time: 05:00 PM

Estimate: 0.00

Tag number: T1

Promised date: 10/31/2016

Customer Comments: No

~~~~~  
A SERVICE CALL

|         |     |                             |      |        |
|---------|-----|-----------------------------|------|--------|
| M-69-12 | CPE | SERVICE CALL/ ENGINE REPAIR | 1.65 | 237.60 |
|---------|-----|-----------------------------|------|--------|

Tech(s): 622

|      |    |                        |  |       |
|------|----|------------------------|--|-------|
| MISC | CP | MILEAGE 20 KM @ \$1/KM |  | 20.00 |
|------|----|------------------------|--|-------|

|      |      |      |        |        |       |               |        |
|------|------|------|--------|--------|-------|---------------|--------|
| Pts: | 0.00 | Lbr: | 237.60 | Other: | 20.00 | Total Line A: | 257.60 |
|------|------|------|--------|--------|-------|---------------|--------|

Story: 827146 DROVE OUT HOOKED UP LAPTOP, READ THE CODES,(ALL-INACTIVE) & RAN A CUT OUT TEST.1,2,&3 INJECTORS ARE NOT FIRING. REMOVE VALVE COVER, UN-HOOKED INJECTORS 1,2,&3 IN SEQUENCE TO SEE IF THE BAD INJECTOR COULD BE IDENTIFIED. CUSTOMER SAID #2 WAS WET. RECOMMENDED CHANGING #2 INJECTOR FIRST. #4,5,&6 VALVE ROCKER BAR WAS INSTALLED UPSIDE DOWN, RECOMMENDED FLIPPING IT AS WELL. CUSTOMER WILL BOOK LATER FOR POSSIBLE REPAIRING OF ENGINE.

~~~~~  
Customer Pay

Labor	237.60
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	39.01
Deductible	0.00
Total Charges	276.61
Less Insurance/Adjustment	0.00
Sales Tax	13.83
Total	290.44