

Repair Order Detail - Internal Copy

RO Number: 716016

RO Status: CLOSED

Customer: H & B OILFIELD SERVICES

[Click to View Cust Copy](#)

Phone(s): Contact: (403)998-9022

Main: (403)998-9022

Cell:

Vehicle: 1FUJA6CK38LZ79887

2008 COLUM

HB156

Mileage: 1

Payment type: 6C

Waiter: No

Service advisor: 1015

Promised time: 05:00 PM

Estimate: 0.00

Tag number:

Promised date: 07/31/2014

Customer Comments: No

~~~~~  
A REPLACE CUSTOMER SUPPLIED INJECTOR AT CUSTOMERS REQUEST  
M-69 CPE REPAIR 2.50 360.00

Tech(s): 846

Pts: 0.00 Lbr: 360.00 Other: 0.00 Total Line A: 360.00

Story: 1 REMOVED AND REPLACED #4 INJECTOR. REINSTALLED VALVE  
COVER. RUN AFTER - RUNS GOOD.

~~~~~  
B CHECK FOR AIR DRYER LEAKING
M-69 CP REPAIR 0.50 69.50

Tech(s): 846

FAR14686C 1 AB CONN, 3.51

Pts: 3.51 Lbr: 69.50 Other: 0.00 Total Line B: 73.01

Story: 1 CHECKED AIR DRIER SYSTEM. REPAIRED AIR LEAK AT BACK OF
TRANSMISSION. AIR DRIER NEEDS REPLACED.

~~~~~  
Customer Pay  
Labor 429.50  
Parts 3.51  
Lube 0.00  
Sublet 0.00  
Miscellaneous/Shop Charge 34.36  
Deductible 0.00  
Total Charges 467.37  
Less Insurance/Adjustment 0.00  
Sales Tax 23.38  
Total 490.75