W10-80885

Accurate Mechanical & Welding

97 PRAIRIE PLACE SE CALGARY, ALBERTA. T1X-0K2 (403) 243-1717



INVOICE #8516

office@amwi.ca amwi.ca GST# 10054 5730 RT0001

PAGE 2 OF 3

CUSTOMER: 1129037 ALBERTA LTD SUITE 300, 1324 - 11 AVENUE SW CALGARY, AB. T3C 0M6 Cell: (403) 804-5872		YEAR: MAKE/MODEL: VIN: ENGINE:	2001 kenworth w900 1nkwl00x21j8880885 880885	LICENS	/DRIVE: / :E: N/OUT: 0
		ENGINE.	000000		
PART	5" EXHAUST ELBOW	1	@ \$75.93	\$75.93	NEW
PART	5" EXHAUST CLAMP	2	@ \$14.63	\$29.26	NEW
PART	5" MUFFLER	1 @ \$116.21		\$116.21	NEW
LABOR: DUNN, MI	REPAIR EXHAUST LEAK	5	@ 110.00	\$550.00	LABOR
			T	otal for "REPAIR EXHAU	ST LEAK": \$771.40
VEHICLE ISSUE #6 RE	PLACE CONVEX MIRROR				
TECH REPORT: REMO	VED CRACKED MIRROR AND REI	PLACED WITH NEV	V.		
PART	8" CONVEX MIRROR	1 (@ \$20.70	\$20.70	NEW
LABOR: DUNN, MI	REPLACE CONVEX MIRROR	0.5 (@ 110.00	\$55.00	LABOR
			Total	for "REPLACE CONVEX	MIRROR": \$75.70
VEHICLE ISSUE #7 RE	PLACE RIGHT FRONT HUB				
TECH REPORT: REMO'	VED CAP AND CLEANED IT AS W	ELL AS MOUNTING	SURFACE, REPLACED	GASKET AND INSTALL	ED. FILLED UP
TIOD TITLE OIL					
PART	HUB CAP GASKET	1	@ \$3.70	\$3.70	NEW
PART	HUB CAP GASKET REPLACE LAKING HUB		@ \$3.70 <u>@</u> 110.00	\$3.70 \$55.00	NEW LABOR
PART			2) 110.00		LABOR
PART LABOR: DUNN, MI		0.5 (2) 110.00	\$55.00	LABOR
PART LABOR: DUNN, MI	REPLACE LAKING HUB	0.5 (i	110.00 Total fo	\$55.00 or "REPLACE RIGHT FR	LABOR ONT HUB": \$58.70
PART LABOR: DUNN, MI VEHICLE SSUE #8 THE TECH REPORT: REMOVE	REPLACE LAKING HUB	0.5 (ES (ES, CLEANED SUF	110.00 Total fo	\$55.00 or "REPLACE RIGHT FR	LABOR ONT HUB": \$58.70
PART LABOR: DUNN, MI VIEHICO F ISSUE #8 HE TECH REPORT: REMOVON AND TORQUED. PART	REPLACE LAKING HUB PLACE FRONT DRUM AND BRAKI VED WHEELS, DRUMS AND BRAKI 16.58#34; X 68#34; BRAKE	0.5 (ES, CLEANED SUF 2 @	Total fo	\$55.00 or "REPLACE RIGHT FRO D NEW SHOES AND DR	LABOR ONT HUB": \$58.70 RUMS. PUT TIRES
PART LABOR: DUNN, MI NEHRO F ISSUE #8 HE TECH REPORT: REMOVED.	REPLACE LAKING HUB PLACE FRONT DRUM AND BRAK VED WHEELS, DRUMS AND BRAK 16.5" X 6" BRAKE SHOE KIT	0.5 (ES, CLEANED SUF 2 @ 2 @	Total for RFACES AND INSTALLE	\$55.00 or "REPLACE RIGHT FRO D NEW SHOES AND DR \$267.96	LABOR ONT HUB": \$58.70 RUMS. PUT TIRES NEW
PART LABOR: DUNN, MI VIEHE E SSUE # HE TECH REPORT: REMOVON AND TORQUED. PART	REPLACE LAKING HUB PLACE FRONT DRUM AND BRAKE VED WHEELS, DRUMS AND BRAKE 16.5" X 6" BRAKE SHOE KIT 16.5 X 6 DRUM REPLACE FRONT	0.5 (ES, CLEANED SUF 2 @ 2 @	110.00 Total for RFACES AND INSTALLE \$133.98 \$271.87	\$55.00 or "REPLACE RIGHT FRO D NEW SHOES AND DR \$267.96 \$543.74	LABOR ONT HUB": \$58.70 RUMS. PUT TIRES NEW NEW LABOR
PART LABOR: DUNN, MI VEHICLE SUE # HE TECH REPORT: REMOVON AND TORQUED. PART PART LABOR: DUNN, MI	REPLACE LAKING HUB PLACE FRONT DRUM AND BRAKE VED WHEELS, DRUMS AND BRAKE 16.5" X 6" BRAKE SHOE KIT 16.5 X 6 DRUM REPLACE FRONT BRAKES & DRUMS	0.5 (ES, CLEANED SUF 2 @ 2 @	110.00 Total for RFACES AND INSTALLE \$133.98 \$271.87	\$55.00 or "REPLACE RIGHT FRO D NEW SHOES AND DR \$267.96 \$543.74 \$247.50	LABOR ONT HUB": \$58.70 RUMS. PUT TIRES NEW NEW LABOR
PART LABOR: DUNN, MI TECH REPORT: REMOVON AND TORQUED. PART PART LABOR: DUNN, MI VEHICLE USSUE #0 NEI TECH REPORT: CHECK	REPLACE LAKING HUB PLACE FRONT DRUM AND BRAKE VED WHEELS, DRUMS AND BRAKE 16.5" X 6" BRAKE SHOE KIT 16.5 X 6 DRUM REPLACE FRONT BRAKES & DRUMS	0.5 (ces, cleaned sur 2 @ 2 @ 2.25 (ces)	110.00 Total for "REPLACE	\$55.00 OF "REPLACE RIGHT FROM D NEW SHOES AND DE \$267.96 \$543.74 \$247.50 FRONT DRUM AND BR	LABOR ONT HUB": \$58.70 RUMS. PUT TIRES NEW NEW LABOR RAKES": \$1,059.20
PART LABOR: DUNN, MI TECH REPORT: REMOVON AND TORQUED. PART PART LABOR: DUNN, MI VEHICLE USSUE #0 NEI TECH REPORT: CHECK	REPLACE LAKING HUB PLACE FRONT DRUM AND BRAKE VED WHEELS, DRUMS AND BRAKE 16.58#34; X 68#34; BRAKE SHOE KIT 16.5 X 6 DRUM REPLACE FRONT BRAKES & DRUMS PAIR HEATER FAN SED FOR VOLTAGE AT BLOWER IN	0.5 (ES, CLEANED SUF 2 @ 2 @ 2.25 (MOTOR, VOLTAGE	110.00 Total for "REPLACE	\$55.00 OF "REPLACE RIGHT FROM D NEW SHOES AND DE \$267.96 \$543.74 \$247.50 FRONT DRUM AND BR	LABOR ONT HUB": \$58.70 RUMS. PUT TIRES NEW NEW LABOR RAKES": \$1,059.20

Recommended Repairs:	Labor	\$2,546.50
	Parts	\$1,846.20
	Sublet	\$0.00
	Total Fees	\$227.64
FROM THE DATE OF DELIVERY FOR A PERIOD OF 30 DAYS, ACCURATE WILL REPAIR ANY DEFECTS IN MATERIALS OR WORKMANSHIP TO THE REPAIRS STATED ON THE INVOICE. CONSEQUENTIAL		\$4,620.34
DAMAGE IS NOT INCLUDED IN THESE WARRANTIES. ALL WARRANTY WORK TO BE DONE IN OUR	GST @ 5%	\$231.02
ISHOP AND WILL NOT COVER ANY THIRD PARTY COSTS. WARRANTY DOES NOT INCLUDE TOWING ICHARGES OR CUSTOMER SUPPLIED PARTS. A STORAGE FEE OF 20.00 PER DAY WILL BE CHARGED.	Total	\$4,851.36
AFTER 5 DAYS AFTER NOTIFICATION THAT ALL WORK IS COMPLETE. NEGLECT OR OPERATOR ABUSE OF VEHICLE WILL IMMEDIATELY VOID ANY AND ALL WARRANTIES. ACCURATE MECHANICAL	Payments	\$0.00
IS NET 30 DAYS FROM INVOICE OUT DATE - 24% INTEREST WILL BE APPLY TO LATE PAYMENTS.	Balance	\$4,851.36

I HEREBY AUTHORIZE AND APPROVE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH ALL NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE THE ABOVE VEHICLE FOR THE PURPOSE OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON THE ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. THE SHOP WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGED TO THE VEHICLE OR ARTICLES LEFT IN THE VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND OUR CONTROL. I HAVE READ THE ABOVE AND ACKNOWLEDGE RECEIPT OF AN ESTIMATE AND ACKNOWLEDGE THE BALANCE OWING FOR REPAIRS, PARTS, ACCESSORIES DESCRIBED IN THIS INVOICE.

Date 9/4/2020