

COLOUR		VEHICLE DESCRIPTION		PLATE	UNIT#	TAG	ODO IN
BAD VIN MEXICO		2008 Dodge Ram 1500 Mega Cab 1/2 Ton - Pickup 5.7 L 345 CID V8 Hemi		HTY327			2180720
VIN		VEHICLE OPTIONS				ADV	ODO AUTH
3D3KS19D38G177350						TV	2180720
TIME IN		PROMISED	TERMS	GST EXEMPT#		P.O.	ODO OUT
8:04 AM			Net 30 days				2180720
QTY	ITEM	DESCRIPTION			WARR	NET	EXT.PRICE
2.3h	06ML	Trans					Declined
1	WPN 58623	WATER PUMP Remove & Replace - V8,5.7L Eng					Declined
-1	XCORE	Water Pump - Remfd					Declined
		Core Exchange WPN 58623 Water Pump - Remfd					Declined
		--serial#: W137275-03					
1	THM 449203	Thermostat - Regular					Declined
1	S	RADIATOR WITH CAP					Declined
1	A000017	Cooling system flush					Declined
1h	--MRF	Cooling Service					Declined
1	--??????	Fluids / Oil					Declined
8	--??????	Fluids / Oil					Declined
1	REC	ENVIRONMENTAL SURCHARGE					Declined
		Subtotals Tax out 0.00 Tax in 0.00					
		(Declined: Tax out 1034.29 Tax in 1086.00)					

		TECH NOTED LOW OIL ON DIPSTICK. NO STICKER					
1	BASIC	Oil Change - Basic					Declined
1	--LOF	Oil Change Labor					Declined
5	--??????	Fluids / Oil					Declined
1	--??????	Oil Filters					Declined
1	--mavr	AVR analysis					Declined
		Inspection and test of alternator output,					
		load test battery, test starter draw.					
		Includes printout.					
1	--c-aims	Comprehensive Automotive Inspection & Maintenance					Declined
1	REC	ENVIRONMENTAL SURCHARGE					Declined
		Subtotals Tax out 0.00 Tax in 0.00					
		(Declined: Tax out 74.95 Tax in 78.70)					

		TECH NOTED RIGHT OUTER TIE ROD HAS PLAY, LEFT					
		INNER AND OUTER TIE ROD HAS PLAY. RIGHT FRONT					
		U-JOINT HAS LOTS OF PLAY AND IS WORN.					
1	NCP 2693740	Tie Rod End - Outer					Declined
1	PFC DS1464	Tie Rod End - Inner					Declined
1	PFC DS1463	Tie Rod End - Outer					Declined
1	NCP 2691123	Tie Rod Adjusting Sleeve - Front Suspension					Declined
1	UJN UJ330A	U-Joint - Front					Declined
1.3h	03ML	Center Link - R&R R2500,R3500,4WD					Declined
		DOES NOT include alignment.					
1.3h	03ML	Drag Link - R&R R2500,R3500,4WD					Declined
		DOES NOT include alignment.					
BILL TO:						PARTS:	
						LABOUR:	
						OTHER:	
						SUB-TOTAL:	
						GST/HST:	
						PST:	
						TOTAL:	Cont'd

COLOUR	VEHICLE DESCRIPTION		PLATE	UNIT#	TAG	ODO IN
BAD VIN MEXICO	2008 Dodge Ram 1500 Mega Cab 1/2 Ton - Pickup 5.7 L 345 CID V8 Hemi		HTY327			2180720
VIN	VEHICLE OPTIONS				ADV	ODO AUTH
3D3KS19D38G177350					TV	2180720
TIME IN	PROMISED	TERMS	GST EXEMPT#		P.O.	ODO OUT
8:04 AM		Net 30 days				2180720
QTY	ITEM	DESCRIPTION		WARR	NET	EXT.PRICE
0.9h	03ML	Tie Rod &/Or Ends - R&R R2500,R3500,4WD,One Includes: Adjust toe-in only. NOTE: Deduct .4 if alignment is also performed. NOTE: Manufacturer recommends removal of Rack and Pinion Steering Gear when replacing Inner Tie Rod End(s) on some models. If removal of the Rack and Pinion Gear is necessary, use Steering Gear - R&R plus combinations.				Declined
2.5h	07ML	Axle Shaft Assembly - R&R R2500,R3500,Both Sides,Front Axle				Declined
1	MA4	4 Wheel Alignment Adjust toe and camber into manufacturers reccomendations. Front end inspection. Subtotals Tax out 0.00 Tax in 0.00 (Declined: Tax out 1441.42 Tax in 1513.49. ***** RIGHT REAR LIGHTS ARE INOPERABLE. RIGHT LOWER BEAM IS INOPERABLE. HIGH MOUNT LENSE IS DAMAGED. AIR FILTER IS DIRTY. FRONT DIFF PINION SEAL IS SWEATING. REAR DIFF PINION SEAL IS SWEATING. THROTTLE BODY IS VERY DIRTY. WHEN WAS LAST TUNE UP?				Declined
1	SSS	Shop Supplies / Environmental Levy TOTAL DISCOUNT GIVEN---> 83.28			33.75	33.75
BILL TO:						
					PARTS:	411.98
					LABOUR:	337.50
					OTHER:	33.75
					SUB-TOTAL:	783.23
					GST/HST:	39.17
					PST:	N/C
					TOTAL:	822.40

COLOUR	VEHICLE DESCRIPTION		PLATE	UNIT#	TAG	ODO IN
BAD VIN MEXICO	2008 Dodge Ram 1500 Mega Cab 1/2 Ton - Pickup 5.7 L 345 CID V8 Hemi		HTY327			2180720
VIN	VEHICLE OPTIONS				ADV	ODO AUTH
3D3KS19D38G177350					TV	2180720
TIME IN	PROMISED	TERMS	GST EXEMPT#		P.O.	ODO OUT
8:04 AM		Net 30 days				2180720
QTY	ITEM	DESCRIPTION		WARR	NET	EXT.PRICE
1h	MLD	NO FUEL PRESSURE. RECOMMENED REPLACING FUEL PUMP Diagnostics NO START				112.50
2h	12ML	FUEL PUMP Remove & Replace - Gas w/Skid Plate				225.00
1	FPN C0476M	Fuel Pump Assembly - Electric In-Tank - OEM Equivalent Subtotals Tax out 749.48 Tax in 786.96 *****			411.98	411.98
3h	02ML	REAR BRAKES ARE AT 1mm CALIPERS SIEZED. DISC ROTOR Remove & Replace - Rear,Both Sides,Full Floating Axle Includes: Repack Wheel Bearings (where applicable) and replace Pads (if necessary). DOES NOT include refinishing. Includes: Replace Pads (if necessary). DOES NOT include refinishing.				Declined
1	FNP SS7867M	Brake Pads - Rear, Premium - OE Semi-Metallic				Declined
2	NDR 748880139	Brake Rotor Only - Rear - Premium Coated				Declined
1	CPR 24275388A	Brake Caliper w/ Hardware Only - Left Rear - Remfd				Declined
-1	XCORE	Core Exchange CPR 24275388A Brake Caliper w/ Hardware Only - Left Rear - Remfd --serial#: W137275-01				Declined
1	CPR 24275387A	Brake Caliper w/ Hardware Only - Right Rear - Remfd				Declined
-1	XCORE	Core Exchange CPR 24275387A Brake Caliper w/ Hardware Only - Right Rear - Remfd --serial#: W137275-02				Declined
1	A000020	Brake Flush				Declined
1	--FLX BF41L	FLEXPAC INC. Brake fluid For All Hydraulic ABS, Drum, Disc Braking Systems & Hydralic Clutches reccomending A DOT 3 & DOT 4 Fluid. 1L per bottle				Declined
1	--MH	Hydraulic Brake Flush				Declined
1	REC	ENVIRONMENTAL SURCHARGE Subtotals Tax out 0.00 Tax in 0.00 (Declined: Tax out 1209.08 Tax in 1269.55) *****				Declined
1.3h	06ML	MULTIPLE COOLANT LEAKS. RADIATOR, WATERPUMP RADIATOR Remove & Replace - V8, Automatic				Declined
BILL TO:					PARTS: LABOUR: OTHER: SUB-TOTAL: GST/HST: PST: TOTAL:	Cont'd