

C396

MIDSUN AUTOMOTIVE

NAME: _____ PHONE#: _____

VEHICLE:

YEAR: 01 MAKE: BMW MODEL: ^{SE} X5 COLOR: _____

VIN: WBAFA53591LM65756 LIC: _____ KM: 228868

ENGINE: 3.0L 4X4 YES / NO .

WORK TO BE DONE:

check over.
check door handles
window gets stuck down.

REPAIRS REQUIRED:

Needs Window Regulator - Taped on
Inside Door Handle Broken - LF
LF Door Latch Assembly Broken

Oil Pan Leaking
LF Axle Seal Leaking
RF Axle Seal Leaking - Axle Goes Through oil Pan
T-Case Leaking

Latch + Handle
51 218 402 537 = 460.80
51 41 8408 565 = 42.20
2 Hr = 290.00

LD

792.20

QUOTE & COMMENTS:

Trans Pan Leaking
LR Lower control Arm Bushing Bad
LD Pressed In knuckle
Front Brakes 70%
Rear Brakes 70%
Front Lower control Arm Bushings Torn

741-488 = 568.80
~~X~~ 1.5 Hr = 217.50
786.30

Front Lower control Arms

$$31\ 12\ 6\ 769\ 717 = 234.72$$

$$31\ 12\ 6\ 769\ 718 = 165.18$$

$$1.5\ Hr = 217.50$$

$$\text{Align} = 145.00$$

$$\underline{762.40}$$

$$\underline{834.90}$$

$$905 - 533 = 127.62$$

$$2.5\ Hr = 362.50$$

$$\underline{490.12}$$

$$\underline{862.62}$$

Front Lower control Arms
Align
1.5 Hr
2.5 Hr