

Ridgeline Equipment Ltd.  
 2770 107 Ave SE  
 Calgary AB T2Z 3R7  
 +1 4037016013  
 admin@ridgelineequip.ca  
 GST/HST Registration No.:  
 781475116RC0001  
 Business Number 781475116RC0001



# INVOICE

**BILL TO**



**INVOICE #** 3022  
**DATE** 03/08/2021  
**DUE DATE** 02/09/2021  
**TERMS** Net 30

**SERIAL#** 3FJ00197      **MAKE/MODEL** Caterpillar 300B Excavator

DATE	PRODUCT/SERVICE	QTY	RATE	TAX	AMOUNT
28/04/2021	<b>Travel</b> Travel to and from jobsite (split between invoices 2480, 2593 & 2594)	0.75	95.00	GST	71.25
28/04/2021	<b>Field Service</b> -Cleaned out inside of left planetary housing. -Replaced all planet gears and bearings in outer housing. -Replaced sun gear with new one. -Cleaned cover and re-installed it onto unit.	1.50	135.00	GST	202.50
06/06/2021	<b>Travel</b> Travel to and from jobsite (split between invoices 2481 & 2594)	1	95.00	GST	95.00
06/06/2021	<b>Field Service</b> -Removed planetary sections from right final drive. -Had to use a solvent sprayer with solvent and brake clean to clean old grease and dirt from the components as it had been sitting open for a long time. -Assembled outer planetary section using new parts. -Found that there is one secondary sun gear missing. -Had to clean, prep and weld the old planetary cover as it had multiple cracks through it.	4.50	135.00	GST	607.50
15/06/2021	<b>Travel</b> Travel to and from jobsite (split between invoices 2594 & 2738)	1	95.00	GST	95.00

PAID

All work is performed upon customer request/specifications and approval.  
 Payment terms Net 30, based on dates services rendered. Please make all cheques out to Ridgeline Equipment Ltd.  
 Please forward all concerns to admin@ridgelineequip.ca.  
 Interest on overdue invoices will be charged at 27.88% per month.  
 All funds are in \$CAD.

DATE	PRODUCT/SERVICE	QTY	RATE	TAX	AMOUNT
15/06/2021	<b>Field Service</b> -Finished assembly of right side final drive after installing sun gear that came in from finning. -Had to reweld the right final drive cover as it was cracked through the last weld. -Filled both final drives with TDTO 30w oil. -Started charging batteries and decided to check engine fluid levels before starting unit. -Added extended life antifreeze to the unit as it was low. -Found that the engine oil was way overfull. -Drained engine oil and coolant came out. -Removed engine oil pan and pressure tested the cooling system and found that multiple engine liners were leaking. -Drained out all the coolant that I put back into the unit.	7.50	135.00	GST	1,012.50
	<b>Part Sales</b> TDTO-30	28	5.68	GST	159.04
	<b>Heavy Duty Pre-Mixed Coolant (Litre) (deleted)</b> Ext Life Coolant	8	18.28	GST	146.24
	<b>Part Sales</b> 0998205 Guide	6	66.14	GST	396.84
	<b>Part Sales</b> 0998196-UCN Gear	6	435.70	GST	2,614.20
	<b>Part Sales</b> 0998193-UCN Gear	2	571.43	GST	1,142.86
	<b>Part Sales</b> 0998189-UCN Carrier	1	928.57	GST	928.57
	<b>Part Sales</b> 0998215-UCN Shim	2	71.43	GST	142.86

---

SUBTOTAL	7,614.36
GST @ 5%	380.72
TOTAL	7,995.08
PAYMENT	7,995.08
BALANCE DUE	<b>\$0.00</b>

All work is performed upon customer request/specifications and approval.  
Payment terms Net 30, based on dates services rendered. Please make all cheques out to Ridgeline Equipment Ltd.  
Please forward all concerns to admin@ridgelineequip.ca.  
Interest on overdue invoices will be charged at 27.88% per month.  
All funds are in \$CAD.