



**Brown's Industrial Sales**

Highway 16 W & Range Road 20  
 P.O. Box 21092 Lloyd Mall  
 Lloydminster, AB T9V 2S1  
 780-875-2339 • Fax: 780-875-0262

**PLEASE REMIT TO:**  
 63214 Highway 892 • P.O. Box 1267  
 Cold Lake, AB T9M 1P3  
 780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 91-019

|                   |                |             |
|-------------------|----------------|-------------|
| Branch            |                |             |
| COLD LAKE         |                | *REPRINT*   |
| Date              | Time           | Page        |
| 06/13/16          | 07:09:38 (B)   | 01          |
| Account No        | Phone No       | Inv No      |
| INT01             | 000 0000000    | W02590      |
| Ship Via          | Purchase Order |             |
| Tax Exempt ID No. |                |             |
|                   |                | Salesperson |
|                   |                | 102         |

**SERVICE INVOICE**

|             |      |               |                     |     |
|-------------|------|---------------|---------------------|-----|
| STK#/FLEET# | HRS  | PIN/EIN       | WARRANTY DATE       | HRS |
| R0000377    | 2005 | TRAVIS CLAM D | X 48XEF393351003706 |     |
| 91-019      | XXXX | 51491         |                     |     |

REPAIR# 1 C CAL01 N/A 06/10/16 06/10/16

Test Operations

COMPLAINT:

Test operations, seem not to be working with controller

CORRECTION:

JUNE 10/16 C.B, REWIRED THE TRAILER SO IT WORKED, SHOWED GARRY HOW TO RUN IT, REINSTALLED THE SIX WIRE PLUG.

|          |                 |        |
|----------|-----------------|--------|
|          | LABOR           | 133.75 |
| 50210501 | REPAIR TOTAL==> | 133.75 |

REPAIR# 2 C CAL01 TRLSER 06/10/16 06/10/16

Montly Trailer Service

1.00 HRS

CORRECTION:

JUNE 10/16 C.B, CHECKED THE TRAILER OVER, REPAIRED AIR LEAK ON THE LEFT CENTRE AXLE BRAKE POT, TOP UP ALL THE HUB OILS, INSPECTED THE BRAKES, CHECKED THE TIRE PRESSURES, THE RIGHT CENTRE AXLE OUTER TIRE IS CUPPING, CHECKED ALL THE LIGHTS, GREASED UNIT AND LUBED THE TARP CHAIN, REPLACED THE BROKEN GREASE NIPPLE ON THE RIGHT REAR SLACK ADJUSTER.

|          |                 |        |
|----------|-----------------|--------|
|          | LABOR           | 145.00 |
| 50210501 | REPAIR TOTAL==> | 145.00 |

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

|                |          |          |
|----------------|----------|----------|
|                | INTERNAL | CUSTOMER |
| LABOR          | 278.75   |          |
| SHOP SUPPLIES  | 13.93    |          |
| INTERNAL TOTAL | 292.68   |          |

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By