



Brown's Industrial Sales

Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 91-015

Branch		
COLD LAKE		*REPRINT*
Date	Time	Page
04/24/16	07:02:14 (B)	01
Account No	Phone No	Inv No
INT01	000 0000000	W02315
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson
		401

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
R0000375	2005 ARNES TRI AXL	43151	2A91747335A003868		
91-015	CLAM DUMP	46512			

REPAIR# 1 C ELL01 CVIP-TRL3 04/12/16 04/12/16
 Commercial Vehicle Inspection - 3 Axles 2.80 HRS

CORRECTION:

APR.12 BE. COMPLETED CVI. SERVICED UNIT. TESTED OPERATION OF CLAM DOORS. OK. UNIT HAD NOT MOVED SINCE LAST CVI. TOOK TO ARDMORE AND BACK. RE TORQUED UNIT.

AS1036	SLACK ADJUSTER	RETAIL	92.81	
		1	77.34	77.34
			PARTS	77.34
			LABOR	702.50
50210501		REPAIR TOTAL==>		779.84

REPAIR# 2 C ELL01 NA 04/12/16 04/13/16
 Air Brakes

COMPLAINT:

-2 Air lines kinked @ bulkheads (.75)
 -2 Air lines heavily chaffed (.75)
 -RH Front slack adjuster not ratcheting (1.0)

CORRECTION:

BE. REPLACED 1 BULKHEAD FITTING AT REAR AXLE. REMOVED AND REPLACED 2 BULKHEAD FITTINGS AT CENTRE AXLE. REPLACED BOTH CHAFFED AIR LINES AT RIGHT SIDE CENTRE BRAKE POT. BEAT RIGHT FRONT SLACK ADJUSTER OFF OF S-CAM. INSTALLED NEW ONE AND ADJUSTED AS REQUIRED. TEED UP AIR LINES AND ABS WIRING.

SLN451044	1/2" RUBBER AIR	RETAIL	2.04	
		4	1.70	6.80
	1/2" RUBBER AIR HOSE			
	BY THE FOOT			
410762	1/2 ID AIR BK H	RETAIL	5.89	

CONTINUED ON PAGE 02

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Brown's Industrial Sales

Highway 16 W & Range Road 20

P.O. Box 21092 Lloyd Mall

Lloydminster, AB T9V 2S1

780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:

63214 Highway 892 • P.O. Box 1267

Cold Lake, AB T9M 1P3

780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 91-015

Branch COLD LAKE		
Date 04/24/16	Time 07:02:14 (B)	Page 02
Account No INT01	Phone No 000 0000000	Inv No W02315
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson 401

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
R0000375	2005 ARNES TRI AXL	43151	2A91747335A003868		
91-015	CLAM DUMP	46512			
		2	4.91	9.82	
	1/2 ID AIR BK HSE SLEEVE				
440779	1/2X3/8 AR BRK	RETAIL	7.12		
		3	5.93	17.79	
	1/2X3/8 AR BRK BRASS MALE CONNT				
5129439	BRASS CONNECT	RETAIL	18.59		
		2	15.49	30.98	
67888	3/8 X 1-1/4 BUL	RETAIL	8.64		
		3	7.20	21.60	
	3/8 X 1-1/4 BULKHEAD BRASS ADPATER				
			PARTS	86.99	
			LABOR	331.25	
	50210501		REPAIR TOTAL==>	418.24	

REPAIR# 3 C ELL01 NA 04/12/16 04/13/16

Lamps

COMPLAINT:

- License light inoperative (.5)
- Requires reflective tape on rear (.5)

CORRECTION:

APR.13 BE. REPLACED LICENSE LIGHT BULB. INSTALLED WHITE CONSPICUITY TAPE ON REAR OF UNIT.

98100	2" X 150' WHITE	RETAIL	.10		
		48	.08	3.84	
	2" X 150' WHITE REFLECTIVE TAPE				
	PER INCH				
			PARTS	3.84	
			LABOR	87.50	
	50210501		REPAIR TOTAL==>	91.34	

REPAIR# 4 C MIL01 NA 04/12/16 04/22/16

CONTINUED ON PAGE 03

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Brown's Industrial Sales

Highway 16 W & Range Road 20

P.O. Box 21092 Lloyd Mall

Lloydminster, AB T9V 2S1

780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:

63214 Highway 892 • P.O. Box 1267

Cold Lake, AB T9M 1P3

780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 91-015

Branch COLD LAKE		
Date 04/24/16	Time 07:02:14 (B)	Page 03
Account No INT01	Phone No 000 0000000	Inv No W02315
Ship Via	Purchase Order	
Tax Exempt ID No.		
	Salesperson 401	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
R0000375	2005 ARNES TRI AXL	43151	2A91747335A003868		
91-015	CLAM DUMP	46512			

Welding Repairs

COMPLAINT:

- LH Centre brake pot bracket cracked (1.25)
- Rear clam hinge is cracked (1.25)

CORRECTION:

15/04/2016. J.M. - CRACKS ON TRAILER WHERE CENTRE DUMP PIVOTS ON HINGES. OPENED UP CENTRE DUMP WITH BEN, ALLOWED FOR MORE ROOM TO WORK ON CRACKS. CRACKS GROUND OUT WITH DYE GRINDER, FILLED WITH WELD. PAINTED TO PREVENT FUTURE RUST IN AREA.

	LABOR	250.00
50210501	REPAIR TOTAL==>	250.00

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	168.17	
LABOR	1371.25	
SHOP SUPPLIES	50.00	
INTERNAL TOTAL	1589.42	

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By