



Highway 16 W & Range Road 20  
 P.O. Box 21092 Lloyd Mall  
 Lloydminster, AB T9V 2S1  
 780-875-2339 • Fax: 780-875-0262

**Brown's Industrial Sales**

**PLEASE REMIT TO:**

63214 Highway 892 • P.O. Box 1267  
 Cold Lake, AB T9M 1P3  
 780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 22-014

Branch		
COLD LAKE		*REPRINT*
Date	Time	Page
03/09/17	08:47:45 (B)	01
Account No	Phone No	Inv No
INT01		W03578
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson
		102

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014 2006 KENWOR	9311	1XKDPB0X46R987300		
22-014	T800B	915910			

REPAIR# 1 C SPI01 NA 02/27/17 02/27/17

Service Done Feb 27th 2017 at 9274 hours

COMPLAINT:

Service unit, replace fuel filters and winterize.

CORRECTION:

J.S FEB 27/17 SERVICED UNIT. CHANGED OIL AND FILTER AND PUT 36 L OF 0 W-40 IN. CHANGED FUEL AND AIR FILTERS. GREASED UNIT CHECKED ALL FLUIDS. TOPPED UP WASHER FLUID. PUNCHED FIRE EXTINGUISHER. CHECKED TIRE PRESSURES AND TREAD DEPTHS. FOUND LEFT FRONT DRIVE BRAKE POT LOOSE WHERE MOUNTED. TIGHTENED UP NUTS ON BRAKE POT. WEBASTO NOT WORKING AND BOTH WINDSHIELDS HAVE CHIPS IN THEM.

ADDITIONAL DESCRIPTION:

Service Done Feb 27th 2017 at 9274 hours

EHC05	ENVIRONMENT HAN	RETAIL	.06		
		36	.05	1.80	
EHC100	ENVIRONMENT HAN	3	1.00	3.00	
FF5319	FUEL FILTER	RETAIL	13.08		
		1	10.90	10.90	
FS1000	FUEL FILTER	RETAIL	15.44		
		1	12.87	12.87	
LF9691A	OIL FILTER	RETAIL	33.22		
		1	27.68	27.68	
P534816	OUTER AIR FILTE	RETAIL	63.22		
		2	52.68	105.36	
	OUTER AIR FILTER				
TRC8454	GREASE TRC	RETAIL	7.56		
		1	6.30	6.30	
	#880 CROWN & CHASIS #1 WINTER GREASE				

CONTINUED ON PAGE 02

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Highway 16 W & Range Road 20  
 P.O. Box 21092 Lloyd Mall  
 Lloydminster, AB T9V 2S1  
 780-875-2339 • Fax: 780-875-0262

**Brown's Industrial Sales**

**PLEASE REMIT TO:**

63214 Highway 892 • P.O. Box 1267  
 Cold Lake, AB T9M 1P3  
 780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 22-014

Branch COLD LAKE		
Date 03/09/17	Time 08:47:45 (B)	Page 02
Account No INT01	Phone No	Inv No W03578
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson 102

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014 2006 KENWOR	9311	1XKDPBOX46R987300		
22-014	T800B	915910			
	WINTER				
15-204	WINDSHIELD WASH	RETAIL	3.42		
		1	2.85	2.85	
	WINDSHIELD WASHER FLUID -40 C				
500007872	ROTELLA T5 0W40	RETAIL	8.24		
		36	6.87	247.32	
	ROTELLA T5 0W40 FULL SYNTHETIC BLEND OIL BULK				
			PARTS	418.08	
			LABOR	497.50	
	50210501		REPAIR TOTAL==>	915.58	

REPAIR# 2 C COO02 NA 02/27/17 03/06/17

Light Work

COMPLAINT:

- 1) LH back up light out
- 2) LH fender marker light out

CORRECTION:

(06/03/17-BOB.JR) CHECKED LH BACK UP LIGHT AND ALL WORKING FINE. NOTICED THE LH WORK LIGHT ON CAB WAS NOT WORKING. CLEANED UP GROUND AND TESTED WORKS AGAIN. LH FENDER MARKER HAD FEW BROKE WIRES. SPLICED IN NEW WIRE AND PUT A NEW WEATHER BACK CLIP ON. TESTED LIGHTS WORK FINE NOW.

	LABOR	437.50
50210501	REPAIR TOTAL==>	437.50

REPAIR# 3 C COO02 NA 02/27/17 03/01/17

Cab Repairs

COMPLAINT:

- 1) Gear shifter boot has a large hole

CONTINUED ON PAGE 03

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Highway 16 W & Range Road 20  
 P.O. Box 21092 Lloyd Mall  
 Lloydminster, AB T9V 2S1  
 780-875-2339 • Fax: 780-875-0262

**Brown's Industrial Sales**

**PLEASE REMIT TO:**

63214 Highway 892 • P.O. Box 1267  
 Cold Lake, AB T9M 1P3  
 780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 22-014

Branch COLD LAKE		
Date 03/09/17	Time 08:47:45 (B)	Page 03
Account No INT01	Phone No	Inv No W03578
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson 102

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014 2006 KENWOR	9311	1XKDPBOX46R987300		
22-014	T800B	915910			
2) Cab shocks weak? Replace?					
<u>CORRECTION:</u>					
(06/03/17-BOB.JR) CHANGED SHOCKS ON UNIT. DID NOT HAVE TIME TO INSTALL SHIFTER BOOT.					
K04279	SHIFTER BOOT		RETAIL	38.88	
			1 N	32.40	32.40
T71-1000	CAB SHOCK		RETAIL	82.25	
			2 N	68.51	137.02
				PARTS	169.42
				LABOR	10.00
	50210501		REPAIR TOTAL==>		179.42

REPAIR# 4 C ELL01 N/A 02/27/17 03/06/17

Steering Issues

COMPLAINT:

Steering pull?? Road test to verify, RH front tire wearing funny.

ADDITIONAL DESCRIPTION:

MAR.06 BE. DRIVER COMPLAINED THAT STEERING PULLS TO THE RIGHT AND WILL NOT RETURN TO CENTER ON IT'S OWN. RAISED FRONT END, KNOCKED DRAG LINKS OFF AT STEERING KNUCKLES, MOVED KINK PINS FROM LOCK TO LOCK TO VERIFY THAT THEY WERE FREE, OK. REMOVED STEERING SHAFT AND INSPECTED UNIVERSAL JOINTS, BOTH WERE GOOD, CYCLED BOTH STEERING BOXES BACK AND FOURTH, BOTH WERE CONSISTENTLY SMOOTH. REINSTALLED STEERING SHAFT AND DRAG LINKS WITH NEW COTTER PINS, CHECKED TIRE PRESSURES RIGHT WAS AT 120 AND LEFT WAS AT 85. SUSPECTED THAT THE PULL WAS CAUSED BY THE TIRES, CHECKED TOE BEFORE INSTALLING TIRES, OK, 1/16" IN.

JR = REMOVED STEER TIRES AND INSTALLED NEW STEER TIRES AND

CONTINUED ON PAGE 04

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Highway 16 W & Range Road 20  
 P.O. Box 21092 Lloyd Mall  
 Lloydminster, AB T9V 2S1  
 780-875-2339 • Fax: 780-875-0262

**Brown's Industrial Sales**

**PLEASE REMIT TO:**

63214 Highway 892 • P.O. Box 1267  
 Cold Lake, AB T9M 1P3  
 780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 22-014

Branch COLD LAKE		
Date 03/09/17	Time 08:47:45 (B)	Page 04
Account No INT01	Phone No	Inv No W03578
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson 102

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014 2006 KENWOR	9311	1XKDPB0X46R987300		
22-014	T800B	915910			
PUT BACK ON UNIT. TORQUED TO 500 FT LB.					
CBB12	CONTRACT 12 OZ	RETAIL	15.01		
		2	12.51	25.02	
TDS	TIRE TAX	2	9.00	18.00	
	TIRE DISPOSAL SURCHARGE				
VS542	1.26"ALCOA VALV	RETAIL	4.74		
		2	3.95	7.90	
5531990	385/65R22.5	RETAIL	656.84		
		2	547.37	1094.74	
			PARTS	1145.66	
			LABOR	527.50	
	50210501	REPAIR TOTAL==>		1673.16	

REPAIR# 5 C ELL01 N/A 02/27/17 02/27/17

Coolant Issues

COMPLAINT:

Coolant hose RH side top of engine was leaking on the weekend, hose had to be cut and shortened, check out.

CORRECTION:

MAR.06 BE. CHECKED COOLANT HOSE, LOOKED GOOD, NO REASON TO REPLACE AT THIS TIME.

	LABOR	6.25
50210501	REPAIR TOTAL==>	6.25

***** WORK ORDER TOTALS *****		
	INTERNAL	CUSTOMER
PARTS	1733.16	
LABOR	1478.75	
INTERNAL TOTAL	3211.91	

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By