



Brown's Industrial Sales

Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 22-014

Branch		
COLD LAKE		*REPRINT*
Date	Time	Page
09/18/20	18:01:34 (B)	01
Account No	Phone No	Inv No
INT01		W07518
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson
		102

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014 2006 KENWOR	12475	1XKDPB0X46R987300		
22-014	T800B	974194			

SEGMENT# 1 C SPI01 N/A 09/09/20 09/09/20

Light Issues

COMPLAINT:

The LH high beam is not working and the hood is hard to open

CORRECTION:

J.S SEPT 9/20 SPRAYED DOWN HOOD RUBBERS WITH FLUID FILM AND LITHIUM GREASE. HOOD CROSS BRACE WORN OR BROKE INSIDE HINGE ON L/H SIDE.

FOUND POOR CONNECTIONS AT CONNECTOR UNDER HOOD PUT DIELECTRIC GREASE IN CONNECTORS AS WELL. ALSO A POOR CONNECTION AT THE HIGH BEAM BULB USED EMERY CLOTH TO SHINE UP PRONGS TESTED GOOD NOW.

	LABOR	128.75
50210501	SEGMENT TOTAL==>	128.75

SEGMENT# 2 C STO01 N/A 09/09/20 09/09/20

Coolant Leak & No Start

COMPLAINT:

The unit blew a top rad hose on the way to the range before the gate

CORRECTION:

R.M Sept 11/20 - Drove to location, Installed new hose clamp and topped up coolant.

A.S Sept 11/20 - Pulled in to the shop, Truck started several times no problem. Driver states he had all lights on for over an hour and a half. Batteries were low on charge.

	LABOR	312.50
50210501	SEGMENT TOTAL==>	312.50

CONTINUED ON PAGE 02

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Brown's Industrial Sales

Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 22-014

Branch COLD LAKE		
Date 09/18/20	Time 18:01:34 (B)	Page 02
Account No INT01	Phone No	Inv No W07518
Ship Via	Purchase Order	
Tax Exempt ID No.		
	Salesperson 102	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014 2006 KENWOR	12475	1XKDPB0X46R987300		
22-014	T800B	974194			

SEGMENT# 3 C STO01 N/A 09/09/20 09/09/20

Oil Leak

COMPLAINT:

Some kind of an oil leak at the bottom of the compressor

CORRECTION:

A.S Sept 11/20 - Found the stud was loose that holds the air compressor on. I removed the oil fill spout, Loosened the mounting nuts for the air compressor, Tightened stud back into place, Installed air compressor and tightened nuts. Installed oil fill spout back on.

50210501	LABOR	252.50
	SEGMENT TOTAL==>	252.50

	***** WORK ORDER TOTALS *****	
	INTERNAL	CUSTOMER
LABOR	693.75	
SHOP SUPPLIES	34.68	
INTERNAL TOTAL	728.43	

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By