



Brown's Industrial Sales
 Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 22-014

Branch		
COLD LAKE		*REPRINT*
Date	Time	Page
11/22/21	18:06:47 (B)	01
Account No	Phone No	Inv No
INT01		W08638
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson
		102

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014 2006 KENWOR		X 1XKDPB0X46R987300		
22-014	T800B	992406			

SEGMENT# 1 C CAL01 N/A 11/10/21 11/11/21

Oil Leak Issues

COMPLAINT:

Some kind of oil leak from the engine area

CORRECTION:

NOV 11/21 C.B, REMOVED ALL THE INSULATION ON THE LEFT SIDE OF THE ENGINE BECAUSE ITS SOAKED IN OIL, THE FRONT COVER IS WET AND THE HEAD GASKET IS WET AGAIN LIKE BEFORE, THEN JUST BEFORE THE STARTER IS ALL SOAKED IN OIL AGAIN, CAN'T GET IT TO LEAK A DROP OF OIL RUNNING IN THE SHOP, TOOK UNIT OUT TO THE WASH PAD AND WASHED THE COMPLETE ENGINE AGAIN, MOVED BACK IN THE SHOP, A LOT OF SMOKE COMING OUT THE BLOW BY TUBE, PUT A PLASTIC BOTTLE OVER THE BLOW BY TUBE, RECHECKED FOR LEAKS, GOT RICK TO TEST DRIVE THE UNIT TO SEE IT IT LEAKS UNDER LOAD.

NOV 11/21 C.B, RECHECKED OIL LEAK AFTER RICK GOT BACK FROM THE TEST DRIVE AND THE LEFT SIDE OF THE ENGINE IS COVERED IN OIL, CHECKED THE BOTTLE I HAD ON THE BLOW BY TUBE AND ONLY SOME WATER IN THE BOTTLE NO OIL, LOOKS LIKE IT IS COMING FROM THE EXTRA DIPSTICK HOLE IN THE BLOCK, FILLED THE HOLE WITH SEALANT AND GOING TO LET IS SET UP AND RETEST, ALSO LEAKING OIL BELOW THE AIR COMPRESSOR.

	LABOR	182.50
50210501	SEGMENT TOTAL==>	182.50

SEGMENT# 2 C CAL01 N/A 11/10/21 11/10/21

Repairs

COMPLAINT:

1) Bunk lights are burnt out (DONE)

CONTINUED ON PAGE 02

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

Brown's Industrial Sales

PLEASE REMIT TO:

63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 22-014

Branch COLD LAKE		
Date 11/22/21	Time 18:06:47 (B)	Page 02
Account No INT01	Phone No	Inv No W08638
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson 102

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014	2006 KENWOR	X 1XKDPB0X46R987300	
22-014	T800B	992406		
2) LH front steering hub leaking oil (DONE)				
3) Air leak from under the cab area??				
<u>CORRECTION:</u>				
NOV 10/21 C.B, INSTALLED THE NEW BUNK LIGHT BULBS, THE LIGHT IS STILL NOT WORKING DID THE SAME THING I DID BEFORE WHEN DIAGNOSED WHEN I ORDERED THE BULBS, HAS POWER AND GROUND AT THE LIGHT, REMOVED THE LIGHT AND JUMPED TO A BATTERY AND NOW THE LIGHT WORKS IT NEVER WORK THE LAST TIME I JUMPED THE LIGHT WITH THE OLD BULBS IN IT, MUST NOT BE GETTING ENOUGH VOLTAGE MAYBE.				
NOV 11/21 C.B, TRACKED DOWN POWER PROBLEM TO THE FUSE PANEL, A LOT OF CORROSION IN THE FUSE PANEL, CLEANED AS GOOD AS POSSIBLE AND SPRAYED ELECTRICAL GREASE IN THE CONNECTIONS, REPLACED THE COOLANT WATER VALVE GOING INTO THE HEATER CONTROL. CHECKED FOR AIR LEAK, NO LEAKS FOUND MUST ONLY LEAK WENT COLD?				
BUNKBULB	BUNKBULB	RETAIL	12.00	
		2 T	10.00	20.00
SR2000028	WATER VALVE	RETAIL	214.13	
		1 T	178.44	178.44
		PARTS		198.44
		LABOR		508.75
50210501		SEGMENT TOTAL==>		707.19

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	198.44	
LABOR	691.25	

CONTINUED ON PAGE 03

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.
 I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Brown's Industrial Sales

Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 22-014

Branch COLD LAKE		
Date 11/22/21	Time 18:06:47 (B)	Page 03
Account No INT01	Phone No	Inv No W08638
Ship Via	Purchase Order	
Tax Exempt ID No.		
	Salesperson 102	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
000224	22-014 2006 KENWOR		X 1XKDPB0X46R987300		
22-014	T800B	992406			
				SHOP SUPPLIES	34.56
				INTERNAL TOTAL	924.25

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.
 I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By