



**Brown's Industrial Sales**

Highway 16 W & Range Road 20  
 P.O. Box 21092 Lloyd Mall  
 Lloydminster, AB T9V 2S1  
 780-875-2339 • Fax: 780-875-0262

**PLEASE REMIT TO:**  
 63214 Highway 892 • P.O. Box 1267  
 Cold Lake, AB T9M 1P3  
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 10-070

Branch		
COLD LAKE		*REPRINT*
Date	Time	Page
06/12/23	07:01:42 (B)	01
Account No	Phone No	Inv No
INT01		W10812
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson
		102

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
R0000052	10-070 F350 4X4	8038	1FT8W3B67DEB48336		
10-070	F350	122640	6.2L V8		

SEGMENT# 1 C WER01 N/A 05/04/23 05/04/23

Service Unit

CORRECTION:

GW May 5/23

- Service unit as per Brown's check list.
- Advise supervisor of issues for repair.
- Change engine oil and filter.
- Reset engine oil life monitor and update service decal.
- Check all drive line fluids, top up washer fluid.
- Change air filter.

	LABOR	206.40
50210501	SEGMENT TOTAL==>	206.40

SEGMENT# 2 C WER01 N/A 05/04/23 05/04/23

Battery/ Electrical & Repairs

COMPLAINT:

- 1) The battery light is on all the time
- 2) Rear brake pads worn down
- 3) Both front marker lights need proper amber bulb
- 4) LH front wheel bearing is badly worn
- 5) Interior rear light inop
- 6) LH rear pwr window inop

CORRECTION:

GW May 5/23

- 1) Diagnose battery light issues, test charging system. Alternator fail. 11.90 volts under load. Remove and replace alternator , includes remove alternator from donor vehicle. Install and test system, alternator passed.

CONTINUED ON PAGE 02

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



**Brown's Industrial Sales**  
 Highway 16 W & Range Road 20  
 P.O. Box 21092 Lloyd Mall  
 Lloydminster, AB T9V 2S1  
 780-875-2339 • Fax: 780-875-0262

**PLEASE REMIT TO:**  
 63214 Highway 892 • P.O. Box 1267  
 Cold Lake, AB T9M 1P3  
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 10-070

Branch COLD LAKE		
Date 06/12/23	Time 07:01:42 (B)	Page 02
Account No INT01	Phone No	Inv No W10812
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson 102

**SERVICE INVOICE**

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
R0000052 10-070 F350 4X4	8038	1FT8W3B67DEB48336		
10-070 F350	122640	6.2L V8		
2) replace front park lamp bulbs, includes remove and replace grill and both head lamps. Test operation. Good. Replace right door mirror marker lamp. Needs left front wheel bearing. Rear interior lamp not working, replaced bulb, did not correct issue. Check wiring				
3) Replace left front wheel bearing.				
4) Replace rear brake pads.				
EHC10	ENVIRONMENT HAN	RETAIL	.13	
		2 T	.10	.20
EHC50	ENVIRONMENT HAN	2 T	.50	1.00
FA1883	AIR FILTER	RETAIL	34.74	
		1 T	25.17	25.17
FL820S	OIL FILTER	RETAIL	12.03	
		1 T	8.96	8.96
KLLD1040	KL 5W20 1LITRE	RETAIL	6.11	
		2 T	5.05	10.10
KLLD1060	KL 5W20 JUG	RETAIL	30.43	
		1 T	27.30	27.30
WBR930793	WHL BEARING ASS	RETAIL	557.12	
		1 T	428.55	428.55
WSD1691MH	REAR BRAKE PADS	RETAIL	67.86	
		1 T	52.20	52.20
		PARTS		553.48
		LABOR		960.00
50210501		SEGMENT TOTAL==>		1513.48

SEGMENT# 3 C PAT01 N/A 05/04/23 05/04/23

CONTINUED ON PAGE 03

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.  
 I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



**Brown's Industrial Sales**

Highway 16 W & Range Road 20

P.O. Box 21092 Lloyd Mall

Lloydminster, AB T9V 2S1

780-875-2339 • Fax: 780-875-0262

**PLEASE REMIT TO:**

63214 Highway 892 • P.O. Box 1267

Cold Lake, AB T9M 1P3

780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 10-070

Branch COLD LAKE		
Date 06/12/23	Time 07:01:42 (B)	Page 03
Account No INT01	Phone No	Inv No W10812
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson 102

**SERVICE INVOICE**

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
R0000052	10-070 F350 4X4	8038	1FT8W3B67DEB48336		
10-070	F350	122640	6.2L V8		

Tire Issues

CORRECTION:

RH rear tire going flat  
 CP MAY 26/23 SPARE TIRE ON UNIT (R/R) PULLED TIRE FROM BOX  
 STILL HAD AIR 80PSI BUT TIRE WORN UNEVENLY LET LEE KNOW,  
 RICK SAID TO THROW TIRE BACK IN BOX , RE-TORQUED TIRES AS  
 PER TORQUE TAG PARKED TRUCK IN HEALING ROW

	LABOR	68.80
50210501	SEGMENT TOTAL==>	68.80

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

	INTERNAL	CUSTOMER
PARTS	553.48	
LABOR	1235.20	
SHOP SUPPLIES	50.00	
INTERNAL TOTAL	1838.68	

**TERMS AND CONDITIONS**

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By