

# KIRK'S TIRECRAFT

Kirk's Tire Edmonton  
 16806 - 118 Avenue Edmonton AB T5V 1M8  
 Phone: (780)488-9911 Fax: (780)488-9904

## INVOICE E041981

(Copy)

CONTACT:

DATE: 19 Feb 11

SOLD TO: TWICIT  
 TWIN CITY EXCAVATING INC.  
 25846 115AVE  
 ACHESON  
 T7X 6C5  
 TEL: 780 4474737

AB

INVOICE TO:

FAX: 780 4825426

PAGE: 1

YEAR	MAKE	MODEL	ENGINE				
PLATE NO	VIN	ODOMETER	UNIT NO.				
		0	111				
TIME IN	PROMISED	TERMS	GST#				
3:21 PM		30 DAYS	860585215				
QTY	ITEM/DESCRIPTION	SIZE	TAX	RETAIL	%	NET	EXT.PRICE
4	100A2015	255/40ZR19XL	G	231.00	30.74	160.00	640.00
4	GT RADIAL Champiro UHPAS 100Y Extra Load		G	4.00	0	4.00	16.00
4	TT		G	12.00		N/C	N/C
4	TIRE RECYCLING FEE		G	25.00		10.00	40.00
4	CP CHANGEOVER PASS TIRE 19 Feb 11		G	4.00	0	4.00	16.00
4	BP BALANCE PASSENGER 19 Feb 11						
4	VSRUB						
4	RUBBER VALVE STEM						

WHEELS MUST BE RE-TORQUED WITHIN 100 KMS

COPY

LEITHBRIDGE 403-327-5985   
 CAROSTON 403-653-4914   
 TABER 403-223-3441   
 BROOKS 403-362-6647   
 REDCLIFF 403-548-3941   
 CALGARY 403-243-8811   
 RED DEER 403-347-1004   
 EDMONTON 780-488-9911

PARTS:	656.00
LABOUR:	40.00
OTHER:	16.00
SUB-TOTAL:	712.00
GST:	35.60
PST:	N/C
TOTAL:	747.60

Name: \_\_\_\_\_ Signature: \_\_\_\_\_

With the above signature I agree to the terms below and acknowledge indebtedness for the total amount owing as shown hereon, or in the amount of any cheque or credit card given in payment and later dishonored. A SERVICE CHARGE OF 26.86% PER ANNUM (2% PER MONTH) WILL BE CHARGED ON PAST DUE ACCOUNTS.



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate  
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

111  
Brodson

Vehicle Type:	Truck	Seating Capacity:	
GVW:	22600 kg	Brake Type:	Air
Owner Name:	Twin City Excavating Inc.		
Address:	25846 115 Avenue		
City:	Acheson	Province:	AB
		Postal Code:	T7X6C5
Telephone Number:	(780) 447-4737		
Vehicle Identification Number:	2FZHATDJ77AY03054		
Make:	Sterling	Model:	Sterling
Year:	2007	Unit Number:	111
Odometer:	156157 KM	Licence Plate Number:	07N581
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	World Gear & Truck Repair Ltd.	Facility Number:	14812
Inspection Technician Name:	Yussef Tarrabain	Technician Number:	A2859
Inspection Technician Signature:			
Inspection Date:	2019/02/11		



## COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

<b>Type of Vehicle</b>	<b>Gross Vehicle Weight registered</b>
Truck	22600 kg

<b>Vehicle Information</b>																	
VIN	2	F	Z	H	A	T	D	J	7	7	A	Y	0	3	0	5	4

<b>Unit Number</b> 111	<b>Year</b> 2007	<b>Make</b> Sterling	<b>Model</b> Sterling	<b>Odometer</b> 156,157
<b>Registered Owner's Name</b> Twin City Excavating Inc.				<b>Plate Number</b> 07N581
<b>Address</b> 25846 115 Avenue			<b>Postal Code</b> T7X6C5	<b>Phone Number</b> (780) 447-4737

Drum Brakes: A-Full Inspection with Drum Removed	Disc Brakes:	
--	--------------	--

	LEFT	FRONT	RIGHT		
100 psi 11 in	16.545 in 5/8 in 3/8 in	Drums/Rotors Linings/Pads Push Rod Travel	16.554 in 5/8 in 3/8 in	100 psi 11 in	
100 psi 100 psi 12 in 13 in	16.572 in 1/2 in 1 3/4 in	Drums/Rotors Linings/Pads Push Rod Travel	16.532 in 11/16 in 1 1/4 in	100 psi 100 psi 17 in 17 in	
100 psi 100 psi 14 in 14 in	16.541 in 5/8 in 1 1/8 in	Drums/Rotors Linings/Pads Push Rod Travel	16.550 in 1/2 in 1 1/4 in	100 psi 100 psi 6 in 6 in	
psi psi in in	in in in	Drums/Rotors Linings/Pads Push Rod Travel	in in in	psi psi in in	
psi psi in in	in in in	Drums/Rotors Linings/Pads Push Rod Travel	in in in	psi psi in in	
psi psi in in	in in in	Drums/Rotors Linings/Pads Push Rod Travel	in in in	psi psi in in	

Park Brake Lining Left na in Right na in Trans na in  
 Wheel Torque Checked  Inner na ft lbs Outer 500 ft lbs



FINNING CANADA LTD. - Fluid Analysis Laboratory, 109-10-170th Street, Edmonton, AB, T5S 1H6, CANADA  
 PHONE: 1-888 FINNING (346-6464)  
 Email: oilsupport@finning.com Web: www.finning.com

**CONTACT INFORMATION**

BILL BECK  
 TWIN CITY EXCAVATING INC  
 108 26230 TWP RD 531A  
 ACHESON, AB  
 CA TX 5A4  
 PHONE: 7804474737  
 FAX: 7804825426  
 Email: BILL@TWINCITYEX.COM

Interp By: Peter Lewandowski



LAB #  
 N030-48347-0290  
 PROCESS DATE 13-Dec-18

DIRT AND WEAR METALS APPEAR TO BE AT ACCEPTABLE LEVELS. OTHER READINGS APPEAR TO BE NORMAL. RESAMPLE AT THE NEXT SERVICE INTERVAL.

**EQUIPMENT**

CUSTOMER EQUIP NUM : 111  
 SERIAL NUMBER : AY30054  
 MODEL : 7500\_STERLING  
 MANUFACTURER : STERLING  
 COMPANY NAME : TWIN CITY EXCAVATING INC  
 JOB SITE :  
 AREA :  
 REGION :

**SAMPLE INFORMATION**

COMPARTMENT NAME : ENGINE  
 COMP SERIAL NUM :  
 COMPARTMENT MODEL :  
 LABEL# : 005117914  
 SHOP JOB NUM :  
 SAMPLE TYPE : OIL  
 SAMPLE SHIP TIME (days) : 7  
 SAMPLE LOCATION :

**WEAR/CONTAMINATION - ADDITIVES/FORMULATION**

SAMPLE DATE	SAMPLE ID	METER (HR)	METERON FLUID	FLUID CHANGE	FLUID BRAND	FLUID TYPE	FLUID CHANGE	VEGET	VEGET CHANGE	FTER	FTER CHANGE	Na	K	SI	AI	Fe	Cr	Pb	Cu	Sn	Ni	Ag	Ti	V	Zn	Ca	Mg	Ba	B	Mo	P
06-Dec-18	N030-48347-0290	18134	500	Y	CHEVRON	DELO 400	Y	15W-40	Y	Y	Y	2	3	11	4	21	3	0	1	0	0	0	0	1	1231	1274	1004	0	34	57	1016
06-Jul-18	N030-48347-0290	17664	0	Y	CHEVRON	DELO 400	Y	5W-40	Y	Y	Y	6	3	26	8	27	6	0	1	0	0	0	1	0	1249	1085	887	0	155	65	1042
19-Sep-17	N030-47283-0015	128227	438	Y	CHEVRON	DELO 400	Y	5W-40	Y	Y	Y	4	2	15	5	19	4	1	1	0	0	0	0	0	1199	1501	427	0	360	84	1006
12-Jul-17	N030-47283-0015	16894	600	Y	CHEVRON	UNKNOWN	Y	15W-40	Y	Y	Y	2	2	5	2	8	1	0	0	0	1	0	0	0	1151	1528	434	0	347	84	1004

**OIL FORMULATION - OIL CONDITION - OIL CONTAMINATION**

SAMPLE DATE	SAMPLE ID	METER (HR)	METERON FLUID	FLUID BRAND	FLUID TYPE	FLUID CHANGE	VEGET	VEGET CHANGE	FTER	FTER CHANGE	Na	K	SI	AI	Fe	Cr	Pb	Cu	Sn	Ni	Ag	Ti	V	Zn	Ca	Mg	Ba	B	Mo	P
06-Dec-18	N030-48347-0290	18134	500	CHEVRON	DELO 400	Y	15W-40	Y	Y	Y	2	3	11	4	21	3	0	1	0	0	0	0	1	1231	1274	1004	0	34	57	1016
06-Jul-18	N030-48347-0290	17664	0	CHEVRON	DELO 400	Y	5W-40	Y	Y	Y	6	3	26	8	27	6	0	1	0	0	0	1	0	1249	1085	887	0	155	65	1042
19-Sep-17	N030-47283-0015	128227	438	CHEVRON	DELO 400	Y	5W-40	Y	Y	Y	4	2	15	5	19	4	1	1	0	0	0	0	0	1199	1501	427	0	360	84	1006
12-Jul-17	N030-47283-0015	16894	600	CHEVRON	UNKNOWN	Y	15W-40	Y	Y	Y	2	2	5	2	8	1	0	0	0	1	0	0	0	1151	1528	434	0	347	84	1004

**OIL CLEANLINESS**

SAMPLE DATE	SAMPLE ID	FLUID CHANGE	FLITER CHANGE	W
06-Dec-18	N030-48347-0290	Y	Y	N
06-Jul-18	N030-48347-0290	Y	Y	N
19-Sep-17	N030-47283-0015	Y	Y	N
12-Jul-17	N030-47283-0015	Y	Y	N

A = Antifreeze, Ag = Silver, Al = Aluminum, B = Boron, Ba = Barium, Ca = Calcium, Cr = Chromium, Cu = Copper, F = Fuel, Fe = Iron, K = Potassium, Mg = Magnesium, Mo = Molybdenum, Ni = Nickel, OXI = Oxidation, P = Phosphorus, Pb = Lead, Si = Silicon, S = Sulfur, Sn = Tin, Ti = Titanium, V = Vanadium, V100 = Viscosity@100C, V40 = Viscosity@40C, VI = Viscosity Index, W = Water, Zn = Zinc

Notice: This analysis is intended as an aid in predicting mechanical wear. No guarantee, expressed or implied, is made against failure of this piece of equipment or a component thereof.



## SHOP WORK ORDER

Qty.	Part No. & Description	price	Driver	Date	Date of HRS	Mechanic	HRS	
1	P7188 oil Filter	5.75		December 6/18	Dec. 6	Daniel	1.0	
1	RS3738 air	5.75	Unit Hours 18/34 hrs.	Closing Date				
1	PF7735 fuel	5.75	Unit Number 111	Year 2007	Make Sterling	Model 7500		
28L	15W-40	5.75	Serial No. 7AY03054	Year 2007	Make Sterling	Model 7500		
			Written By Daniel					
			- Service					
			- replace fuel filter					
			- replace air filter					
			- replace oil and oil filter					
<p style="font-size: 2em; margin: 0;">111</p> <p style="font-size: 2em; margin: 0;">bph</p>								
TOTAL PARTS								







SHOP WORK ORDER

Qty.	Part No. & Description	price	Driver	Date	Date of HRS	Mechanic	HRS
1	C09C07 Door vent	\$30.00		September 12/18	Sept. 12	Daniel	2.5
1	C09C06 Motor	\$158.98	Unit Hours 17977	Closing Date			
			Unit Number 111	Year 2007	Make Sterling	Model 7500	
			Serial No. AY03059		Written By		
			-replace fan door				
			-replace heat control motor				
	TOTAL PARTS	\$188.98					

*111*  
*BRD*



Kirk's Tire Edmonton  
 16806 - 118 Avenue Edmonton AB T5V 1M8  
 Phone: (780)488-9911 Fax: (780)488-9904

**INVOICE E040376 (Copy)**

CONTACT:

DATE: 18 Sep 10

SOLD TO: TWICIT  
 TWIN CITY EXCAVATING INC.  
 25846 115AVE  
 ACHESON  
 T7X 6C5  
 TEL: 780 4474737

AB

INVOICE TO:


FAX: 780 4825426

PAGE: 1

YEAR	MAKE	MODEL	ENGINE
PLATE NO	VIN	ODOMETER	UNIT NO.
TIME IN	PROMISED	TERMS	GST#
8:15 AM		30 DAYS	860585215
			0
			111
			P.O.
			CW
			TAG

QTY	ITEM/DESCRIPTION	SIZE	TAX	RETAIL	%	NET	EXT.PRICE
1	FMT FLAT REPAIR MED TRK	18 Sep 10	G	45.00		45.00	45.00
1	BOOT RADIAL BOOT		G	10.00	0	10.00	10.00
LEFT FRONT INSIDE WO#760239							
WHEELS MUST BE RE-TORQUED WITHIN 100 KMS							

COPY



HBRIDGE CARDSTON TABER BROOKS REDCLIFF CALGARY RED DEER EDMONTON  
 327-5985 403-653-4914 403-223-3441 403-382-6647 403-548-3941 403-243-8811 403-347-1004 780-488-9911

PARTS:	10.00
LABOUR:	45.00
OTHER:	N/C
SUB-TOTAL:	55.00
GST:	2.75
PST:	N/C
<b>TOTAL:</b>	<b>57.75</b>

Name: \_\_\_\_\_ Signature: \_\_\_\_\_  
 With the above signature I agree to the terms below and acknowledge indebtedness for the total amount owing as shown hereon, or in the amount of any cheque or credit card given in payment and later dishonored. A SERVICE CHARGE OF 26.86% PER ANNUM (2% PER MONTH) WILL BE CHARGED ON PAST DUE ACCOUNTS.







Kirk's Tire Edmonton  
 16806 - 118 Avenue Edmonton AB T5V 1M8  
 Phone: (780)488-9911 Fax: (780)488-9904

**INVOICE E039982 (Copy)**

CONTACT:

DATE: 18 Aug 07

SOLD TO: TWICIT  
 TWIN CITY EXCAVATING INC.  
 25846 115AVE  
 ACHESON  
 T7X 6C5  
 TEL: 780 4474737

AB

INVOICE TO:


FAX: 780 4825426

PAGE: 1

YEAR	MAKE	MODEL	ENGINE
PLATE NO	VIN	ODOMETER	UNIT NO.
TIME IN	PROMISED	TERMS	GST#
10:48 AM		30 DAYS	860585215
QTY	ITEM/DESCRIPTION	SIZE	TAX
1	FMT FLAT REPAIR MED TRK	18 Aug 07	G
1	BOOT		G
	RADIAL BOOT		
	RIGHT REAR INSIDE		
	WO#526049		
	WHEELS MUST BE RE-TORQUED WITHIN 100 KMS		

Handwritten signature and initials: BR

COPY



THBRIDGE 327-5985    CARDSTON 403-653-4914    TABER 403-223-3441    BROOKS 403-362-6647    REDCLIFF 403-548-3941    CALGARY 403-243-8811    RED DEER 403-347-1004    EDMONTON 780-488-9911

Name: \_\_\_\_\_ Signature: \_\_\_\_\_

With the above signature I agree to the terms below and acknowledge indebtedness for the total amount owing as shown hereon, or in the amount of any cheque or credit card given in payment and later dishonored. A SERVICE CHARGE OF 26.86% PER ANNUM (2% PER MONTH) WILL BE CHARGED ON PAST DUE ACCOUNTS.

PARTS:	10.00
LABOUR:	45.00
OTHER:	N/C
SUB-TOTAL:	55.00
GST:	2.75
PST:	N/C
<b>TOTAL:</b>	<b>57.75</b>

CRYSTAL GLASS CANADA LTD.  
13022 97 ST NW  
EDMONTON, AB T5E 4C6

Copy 1

(780) 478-5311 FAX:(780) 478-9757

GST/HST ID: 135246221RT0001

Remit To: 6424 Gateway Blvd., Edmonton, AB T6H 2H9

P/O#: Taken By: sephla.tidder Installer:	PST Tax Exempt ID: GST Tax Exempt ID: Ship Via:	Invoice: 2042123941 Date: 7/19/2018
SalesRep:	Adv. Code:	

Bill To: 2049275

Sold To: 2049275

TWIN CITY EXCAVATING LTD  
108 26230 TWP 531A  
ACHESON, AB T7X 5A4

ATTN: BILL  
22010 113 AVE  
EDMONTON, AB T5S 2V7

(780) 447-4737 Fax: (780) 482-5426

Vehicle Information

Make: Sterling Trucks	Model Style: L Series/Heavy Duty Conventional	Year: 2007
Odometer:	VIN:	License:
Fleet Number:	Unit Number: 111	Color:

Qty	Part Number	Description	List	Disc%	Sell	Total
1	DW01254GBNN	Windshield-(Solar Controlled)	*\$249.00	0	\$249.00	\$249.00

\*\* Indicates CPLAB Price List

On Account:	
Sub Total:	\$249.00

GST \$12.45

Total: \$261.45

Customer's Signature: \_\_\_\_\_

Balance: \$261.45









## SHOP WORK ORDER

Qty.	Part No. & Description	price	Driver	Date	Date of HRS	Mechanic	HRS
1	NEW EXHAUST FLANGES	11.83		JUL 13/18			
			Unit Hours 17667	Closing Date JUL 13/18			
			Unit Number 111	Odometer 138699			
			Year 07	Make STERLING			
			Model 7520	Written By BIU			
			Serial No. 2 FZHATDJ7AY 03054				
			- REMOVED TURBO EXHAUST PUMP PIPE AND FLEX PIPE. CUT OFF DAMAGED FLANGE, WELDED ON NEW FLANGE + REINSTALLED WITH NEW FLEX PIPE				
			- CHECKED, CLEANED + TESTED CONTACTS BAR FUEL SENDER UNIT. PUT DISLECTRIC GREASE ON PLUG + SENDER.				
			- SECURED RADIO IN DASH, MADE UP + INSTALLED BRACKETS FOR RADIO FINGER-STRIP				
					JUL 13	BIU	1.0
TOTAL PARTS							

BIU  
BIU



CUSTOMER #: 3519  
UNIT# 111

188977



**Western**  
TRUCK & TRAILER

\*INVOICE\*



18353 - 118 Avenue, Edmonton, AB T5S 1M8  
Phone: (780) 481-7400 Fax (780) 481-7725  
Website: www.westernsterling.com

WINN CITY EXCAVATING INC  
20346 - 115 AVE  
ACHESON, AB T7X 6C5  
HOME: 780-447-4737 CONT: 780-447-4737  
BUS: 780-554-8946 CELL: 780-616-3923

PAGE 1

SERVICE ADVISOR: 1267 TANYA DOOLAN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	KM IN/OUT	TAG
	07	STERLING LT7500	2FZHATDJ77AY03054	PBY030	138687/138687	T054
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
28FEB07 DD		28FEB2009	21:00 10JUL18	**	CHG	12JUL18
R.O. OPENED	READY	OPTIONS:				
10:12 10JUL18	13:52 12JUL18	DLR:33C2 ENG:926916R2001972 1)UNIT #111				

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL  
A DIAG FOR CHECK ENGINE LIGHT COME ON AND OFF ANFD UNIT HAS NO POWER  
6-OCT ENGINE REPAIRS

1259 CH		2472.25	2472.25
1 DDE/RA9061420619 EGR VALVE	1392.28	1392.28	1392.28
CORE CHARGE C		130.00	130.00
2 DDE/A9061421080 GASKET	44.43	37.58	75.16
1 DDE/A9061420880 GASKET	31.21	28.15	28.15
-1 DDE/RA9061420619 CORE RETURN	130.00	130.00	-130.00
1 DDE/A5411870080 GASKET	14.30	11.97	11.97
1 DDE/EA9260967099 TURBO	3253.96	3091.19	3091.19
CORE CHARGE C		390.00	390.00
8 DDE/A0009903150 TURBO NUT	3.75	3.10	24.80
1 A03-23269-000 TUBE ASSY-FORMED AIR I	625.45	510.26	510.26
1 FRCHG FREIGHT	75.00	75.00	75.00
2 535*4* #4 HOSE CLAMP	0.80	0.68	1.36
3 65028 3/8 HTR HOSE	3.25	3.25	9.75
-1 DDE/EA9260967099 CORE RETURN	390.00	390.00	-390.00
1 EXO/3AH00015SP DRAIN ASSY	21.81	17.79	17.79

PARTS: 5237.71 LABOR: 2472.25 OTHER: 0.00 TOTAL LINE A: 7709.96

1 REPAIR FOR CEL ON AND UNIT HAS LOW POWER HOOKED UP TO UNIT AND FOUND ACTIVE CODE FOR EGR VALVE POSITION INCORRECT INSPECTED AND FOUND EGR VALVE HAS FAILED, ALSO FOUND AIR INTAKE PIPE FROM AIR CLEANER TO TURBO HAS RUBBED THROUGH HOLES IN IT, INSPECTED TURBO AND FOUND TURBO IS SEIZED, DRAINED ENGINE COOLANT AND REMOVED AIR INTAKE PIPING AND EGR COOLER ASSEMBLY, REMOVED EGR VALVE AND INSTALLED NEW VALVE INSTALLED EGR COOLER ASSEMBLY, REMOVED TURBO CHARGER AND FOUND OIL IN THE CAC REMOVED CAC AND CLEANED OIL OUT PRESSURE TESTED AND FOUND CAC LEAKS CUSTOMER DOES NOT WANT TO REPLACE CAC AT THIS TIME INSTALLED OLD CAC, WHEN TURBO WAS REMOVED NOTICED TURBO EXHAUST DOWN PIPE FLANGE HALF MISSING UNIT NEEDS NEW EXHAUST PIPE CUSTOMER DOES NOT WANT TO CHANGE EXHAUST PIPE, INSTALLED NEW TURBO AND REASSEMBLED UNIT STEAMED ENGINE OFF AND ROAD TESTED. 15.5

*Handwritten initials/signature*

\*\*\*\*\*  
CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER 197.78

<p>Visit us on the web at: "www.westernsterling.com" Monday to Friday 7:30 am - 9:00 pm</p>		DESCRIPTION	TOTALS
		LABOUR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		TAXES	
		PLEASE PAY THIS AMOUNT	

*Thank You For Allowing Us To Service Your Vehicle*

GST# 867068173RT

CUSTOMER #: 3519  
 UNIT# 111

188977



**Western**  
 TRUCK & TRAILER

\*INVOICE\*



18353 - 118 Avenue, Edmonton, AB T6S 1M8  
 Phone: (780) 481-7400 Fax (780) 481-7725  
 Website: www.westernsterling.com

W CITY EXCAVATING INC  
 20346 - 115 AVE  
 ACHESON, AB T7X 6C5  
 HOME: 780-447-4737 CONT: 780-447-4737  
 BUS: 780-554-8946 CELL: 780-616-3923

PAGE 2

SERVICE ADVISOR: 1267 TANYA DOOLAN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	KM IN/OUT	TAG
	07	STERLING LT7500	2FZHATDJ77AY03054	PBY030	138687/138687	T054
DEL DATE	PROD. DATE	WARR. EXP	PROMISED	PO NO.	PAYMENT	INV DATE
28FEB07 DD		28FEB2009	21:00 10JUL18	**	CHG	12JUL18
R.O. OPENED	READY	OPTIONS: DLR:33C2 ENG:926916R2001972 1)UNIT #111				
10:12 10JUL18	13:52 12JUL18					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
++++++ + WHEELS MUST BE RE-TORQUED + + BETWEEN 50 TO 100 KMS + + CUSTOMER INITIAL + ++++++							

GST ON TOTAL (#: 867068173RT) 395.39



Visit us on the web at:  
 "www.westernsterling.com"

Monday to Friday 7:30 am - 9:00 pm



DESCRIPTION	TOTALS
LABOUR AMOUNT	2472.25
PARTS AMOUNT	5237.71
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	197.78
TOTAL CHARGES	7907.74
LESS INSURANCE	0.00
TAXES	395.39
PLEASE PAY THIS AMOUNT	8303.13

*Thank You For Allowing Us To Service Your Vehicle*

GST# 867068173RT



# SHOP WORK ORDER

Qty.	Part No. & Description	price	Driver	Date Closing Date	Date of HRS	Mechanic	HRS
				July 6/18	July 6	Daniel S	1.0
1	<del>RS 3738</del>	<del>511</del>	Unit Hours 17664				
281	RS 3738	511	Unit Number 111	Make Sterling			
281	RS 3738	511	Year 2007	Model T500			
1	oil filter	21.57	Serial No. AY03059	Written By Daniel			
	A 9051800209B01E05		- Replace oil and oil filter				
1	air hose	55.31	- Replace air filter				
	NG5031-08-08		- repair battery box cover				
			- replaced rear light, fixed wiring				
			- replaced marker bulb				
			- replace front right air line				
	TOTAL PARTS	761.98					

111  
BAC

761.98 \$





SHOP WORK ORDER

Qty.	Part No. & Description	price	Driver	Date	Date of HRS	Mechanic	HRS
1	G1032 Marker light	571.		June 29 2018	June 29	Daniel	0.2
2	clearance light bulb	344.					
			Unit Hours 1765.5 Unit Number 111 Serial No. AY03054	Closing Date Make Sterling Model 7500 Written By Daniel			
			- replace clearance light bulb				
			- replace rear marker light				
			- fix rear marker light wiring				
TOTAL PARTS							

111  
644.