

Repair Order Detail - Internal Copy

RO Number: 150671

RO Status:

Customer: H & B OILFIELD SERVICES

[Click to View Cust Copy](#)

Phone(s): Contact:

Main:

Cell:

Vehicle: 1FUJA6CK38LZ79887

2008 COLUM

HB156

Mileage: 10

Payment type:

Waiter: No

Service advisor: 906

Promised time: 11:00 PM

Estimate:

Tag number:

Promised date: 09/28/2017

Customer Comments: No

~~~~~

|      |                    |      |                    |               |        |  |
|------|--------------------|------|--------------------|---------------|--------|--|
| A    | LOOSE DPF CLEANING |      |                    |               |        |  |
|      | C-DPF              | CPDF | LOOSE DPF CLEANING | 0.00          | 0.00   |  |
|      | Tech(s): 1238      |      |                    |               |        |  |
|      | MISC               | CPDF | DPF CLEANING       |               | 236.00 |  |
| Pts: | 0.00               | Lbr: | 0.00               | Other:        | 236.00 |  |
|      |                    |      |                    | Total Line A: | 236.00 |  |

~~~~~

B	LOOSE DOC CLEANING					
	C-DOC	CPDF	LOOSE DOC CLEANING	0.00	0.00	
	Tech(s): 1238					
	MISC	CPDF	DOC CLEANING		160.00	
Pts:	0.00	Lbr:	0.00	Other:	160.00	
				Total Line B:	160.00	

~~~~~

|                            |        |
|----------------------------|--------|
| Customer Pay               |        |
| Labor                      | 0.00   |
| Parts                      | 0.00   |
| Lube                       | 0.00   |
| Sublet                     | 0.00   |
| Miscellaneous/Shop Charge* | 396.00 |
| Total Charges**            | 396.00 |

\*Miscellaneous/Shop Charge includes tax and/or deductible originally on RO.

\*\*Total Charges includes any Insurance/Adjustment originally on RO.