

Repair Order Detail - Internal Copy

RO Number: 722211

RO Status: CLOSED

Customer: H & B OILFIELD SERVICES

[Click to View Cust Copy](#)

Phone(s): Contact: (403)998-9022

Main: (403)998-9022

Cell:

Vehicle: 1FUJA6CK38LZ79887

2008 COLUM

HB156

Mileage: 1

Payment type: 6C

Waiter: No

Service advisor: 682

Promised time: 08:00 PM

Estimate: 0.00

Tag number: TSHAWN

Promised date: 02/24/2017

Customer Comments: No

~~~~~  
A CUT COUNTERBORES

|              |      |                  |        |                                   |
|--------------|------|------------------|--------|-----------------------------------|
| M-69-12      | CPE  | CUT COUNTERBORES | 4.00   | 576.00                            |
| Tech(s): 719 |      |                  |        |                                   |
| MISC         | CP   | SHIMS, DDC6030B  |        | 80.00                             |
| Pts:         | 0.00 | Lbr:             | 576.00 | Other: 80.00 Total Line A: 656.00 |

Story: 1 DROVE TO H&B SHOP TO CUT COUNTER BORES ON CYLINDER 3 &

4. SET UP TOOL, CUT COUNTER BORES, FIT LINERS WITH SHIMS.

MEASURE & SHIM FOR PROPER PROTRUSION.  
~~~~~

Customer Pay

Labor	576.00
Parts	0.00
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	126.08
Deductible	0.00
Total Charges	702.08
Less Insurance/Adjustment	0.00
Sales Tax	35.10
Total	737.18