



**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Ronco Oilfield Hauling LTD		
Address:	225 Burnt ridge road		
City:	RedDeer	Province:	AB
		Postal Code:	T4S0K6
Telephone Number:	(403) 526-4873		
Vehicle Identification Number:	2D9L40F3731091017		
Make:	Marcep	Model:	Lowbed
Year:	2003	Unit Number:	227
Odometer:	170137 KM	Licence Plate Number:	S65682
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Ronco Oilfield Hauling Ltd.	18696
Inspection Technician Name:	Technician Number:
Lance Szumik	C5931
Inspection Technician Signature:	
Inspection Date:	2020/05/11

162206

Trailer Maintenance Report

Date: Nov 8-19

Unit#: 227

Hubometer: 162206

Next Service Date: _____

Service Type: _____

Serviced By: JS/DS/EB

Tire Air Pressures:

Lights:

- Markers
- Signals
- Brakes
- Wide Load

Comments:

J

1. 110
2. 110
3. 110
4. 110
5. 110
6. 110
7. 110
8. 110
9. 110
10. 110
11. 110
12. 110
13. _____
14. _____
15. _____
16. _____
17. _____
18. _____
19. _____
20. _____
21. _____
22. _____
23. _____
24. _____

Brakes:

- Set Brakes
- Brake Wear

Wheels / Tires:

- Re-torque
- Tread Depth

All @ 500 ft/lbs

T1 - 17mm
 T2 - 15mm
 T3 - 11mm
 T4 - 13mm
 T5 - 10mm
 T6 - 14mm

T7 - 12mm
 T8 - 13mm
 T9 - 6mm
 T10 - 14mm

T11 - 8mm
 T12 - 7mm

Grease / Oils:

- Rolls
- Brakes
- Grease lines
- Hub

J
Full

- Hub: 16 2206 Km

Comments:

Signature: _____

RONCO

OILFIELD HAULING LTD.

REPAIR ORDER

P.O. Box 338
Medicine Hat, Alberta
T1A 7G1

Phone: (403) 526-4873
Fax: (403) 528-2515

DATE May 11/20 DRIVER _____ No. 1789

UNIT # 227 Hours _____ KM's 170,137

DRIVER EXPLANATION:

CVIP.

(ABOVE TO BE COMPLETED FULLY BY DRIVERS)

(Indicate all repairs needed)

MECHANIC'S COMMENTS:

- PSM wheel seal
- MUDFLAP PS REAR
- SET Brakes.
- Citicod Lights.

Direct Parts

① 46300

Cost

Total

(TO BE COMPLETED BY MECHANIC OR DRIVER WHEN COMPLETED)

Total

DATE REPAIRED: _____ MECHANIC'S INITIALS: W

HOURS: _____ KM'S: _____

DATE ROAD TESTED: _____ DRIVER: _____

RONCO

OILFIELD HAULING LTD.

REPAIR ORDER

P.O. Box 338
 Medicine Hat, Alberta
 T1A 7G1
 Phone: (403) 526-4873
 Fax: (403) 528-2515

DATE OCT-8-19 DRIVER _____ No. 1328

UNIT # 227 Hours _____ KM's 16108
161018

DRIVER EXPLANATION: -

Service, D
GREASE.

(ABOVE TO BE COMPLETED FULLY BY DRIVERS)
 (Indicate all repairs needed)

MECHANIC'S COMMENTS:	Direct Parts	Total	Cost
<u>GREASE.</u>			
<u>Tire pressures 110</u>			
<u>Re Torque, 500</u>			
<u>Light check</u>			
<u>Next Service</u>			
<u>164018</u>			

(TO BE COMPLETED BY MECHANIC OR DRIVER WHEN COMPLETED) Total

DATE REPAIRED: _____ MECHANIC'S INITIALS: DS, CS,
 HOURS: _____ KM'S: _____
 DATE ROAD TESTED: _____ DRIVER: _____

