

24 HR. EMERGENCY ROADSIDE SERVICE

AUTOMOTIVE
HEAVY DUTY

INDUSTRIAL
COMMERCIAL

POSTED

**DAN
O
Repair**

Division of 242652 AB Ltd.

Box 351, Lac La Biche, AB T0A 2C0

780-520-DANO (3266)

GST # 104080429

CUSTOMER
NORDEN

ADDRESS		POSTAL CODE	DAY	MONTH	YEAR	PO.#	LABOR HOURS		
			03	06	16		REG	AT	
MAKE OR MFR. NAME	YEAR OR TYPE OF UNIT	MODEL	LOCATION		EMPLOYEE NAME			35	095
CAT	Dozer	D7R	LLB SHOP		DAN OUELLETTE				
SERIAL NUMBER	MILEAGE/HRS.	UNIT / LIC NO.		NORM 780-689-7989					
2EN 732	2819HRS								

DESCRIPTION OF WORK PERFORMED	TRAVEL	KMS	RATE	AMOUNT
* ENGINE OIL DUE AT 2850H ON OIL FILTER *				
MAY 30/16 - REMOVE TRANSMISSION ASSEMBLY, SUPPORTS TRANSMISSION FROM BEVEL & TRANSFER GEAR				NO CHARGE
8.0H - DISMANTLE TRANSFER GEAR & BEVEL GEAR TO CONFIRM BEARING WITH MISSING CASE PACE	PARTS			
- REMOVE COOLER ADAPTOR FOR BEVEL	Qty	DESCRIPTION	PRICE	AMOUNT
- MAKE UP PARTS LIST TO ORDER PARTS		TRANS. S.N. 9TX096/		
JUNE 1/16 - REMOVE ALL BEARINGS & RACES FOR REPLACEMENT		#1, 2, 4 & 5		
8.0H - CLEAN PARTS & PREP FOR NEW BEARINGS		FIBRE DISCS,		
JUNE 2/16 - INSTALL NEW BEARINGS CUPS & CONES		ALL BEARINGS,		
- ASSEMBLE BEVEL GEAR & TRANSFER GEAR INTO HOUSING & WRAP FOR LATER ASSEMBLY		SOALS, TRANSMISSION		
8.0H - DISMANTLE TRANSMISSION ASSEMBLY & WASH UP PARTS TO PREP FOR REASSEMBLY		#4 & #5		
JUNE 3/16 REPLACE ALL BEARINGS & BUSHINGS SUPPLIED		STEEL DISCS		
11.0 REPLACE FRICTION FIFTH & SOLO-ROAD STEEL PLATS.		1328876 HIGH EFFICIENCY FILTER		
ASSEMBLY & MOUNT INTO MACHINERY.		TRANSMISSION	Total Labour	3325
		COOLER	Total Parts	
		UPDATED SPIND	Shop Supplies	35
		SENSOR WALKERS	Travel	
		& SOWERS	SUBTOTAL	3360
			GST	100
			TOTAL	3528

1/ WE HEREBY ACKNOWLEDGE OUR INDEBTEDNESS WHICH WILL RESULT FROM THIS FIELD REPORT INVOICE.
2/ WE HEREBY CERTIFY THAT THE ABOVE WORK WAS COMPLETED TO OUR SATISFACTION.

TERMS: NET 30 DAYS. 2% PER MONTH, 24% PER ANNUM CHARGED ON PAST DUE ACCOUNTS.

CUSTOMER'S SIGNATURE _____ PRINT NAME _____

24 HR. EMERGENCY ROADSIDE SERVICE

AUTOMOTIVE
HEAVY DUTY

INDUSTRIAL
COMMERCIAL

POSTED
DANO
O
Repair

Division of 242652 AB Ltd.

Box 351, Lac La Biche, AB T0A 2C0

780-520-DANO (3266)

GST # 104080429

CUSTOMER
NORDON

ADDRESS _____ POSTAL CODE _____

DAY MONTH YEAR PO.#
08 06 16

LABOR HOURS
REG AT

MAKE OR MFR. NAME YEAR OR TYPE OF UNIT MODEL LOCATION
CAT DOZOR D7R LLB SAOP

EMPLOYEE NAME
DON + DARRYL OUELLETTE 34 0 95 -

SERIAL NUMBER MILEAGE/HRS. UNIT / LIC NO.
2EN732 2819H

NORM - 780-689-7989

DESCRIPTION OF WORK PERFORMED TRAVEL KMS RATE AMOUNT

JUN 6/16 - FINISH TANKS INSTALL
- CALIBRATE DIRECTION SWITCH 14.0 **NO CHARGE**
- ADJUST MODULATION PRESSURE TO 320 PSI
- PERFORM CLUTCH FILL CALIBRATION - ALL GOOD

JUN 7/16 - REPLACE L/R AXLE SEAL & REFILL
- PREP R/H SIDE FOR AXLE SEAL 12.0
- INSTALL TRANS. COOLOR

JUN 8/16 - INSTALL R/H AXLE SEAL & REFILL
- INSTALL AXLES 8.0
- CHECK TORQUE OUTLET PRESSURE: 110 PSI
- ORDER PARTS
- CHECK A/C - GOOD - 46.2° P
- INSTALL CABIN PANELS + INTERIOR
34.0

Total Labour **3230** -
Total Parts
Shop Supplies **30** -
Travel
SUBTOTAL **3260** -
GST **163** -
TOTAL **3423** -

✓ LEFT CYL. LIGHT BROKEN

I / WE HEREBY ACKNOWLEDGE OUR INDEBTEDNESS WHICH WILL RESULT FROM THIS FIELD REPORT INVOICE.
I / WE HEREBY CERTIFY THAT THE ABOVE WORK WAS COMPLETED TO OUR SATISFACTION.

TERMS: NET 30 DAYS, 2% PER MONTH, 24% PER ANNUM CHARGED ON PAST DUE ACCOUNTS.

CUSTOMER'S SIGNATURE _____ PRINT NAME _____