

THUNDER BAY TRUCK CENTRE, Inc. EMAIL: MAIL@TBTC.CA

NUMBER

PHONE P.O. NO.

REPRINT CUSTOMER INVOICE

Peterbilt Thunder Bay 1145 Commerce Street Thunder Bay, ON P7E 6E8 (807) 577-5793 (800) 465-5030 Fax (807) 577-8918

CUSTOMER NAME

SERIAL NO.

Peterbilt Fort Frances 505 McIrvine Road Fort Frances, ON P9A 3X7 (888) 889-2344 (807) 274-7936 Fax (807) 274-2813

Peterbilt Dryden 70 Keith Avenue Dryden, ON P8N 3K8 (807) 223-7577 (844) 223-7577 Fax (807) 223-8482

* INVOICE DATE 09-13-18

REPAIR ORDER NUMBER >>>> DR8108 <<<<

LICENSE

R RATIO

TAG #

OPEN 08-16-18 04:15PM

SVC WTR mta*MT UNIT NO. X: MOUNTAINEERMILEAGE 711402

4:10

YEAR/MAKE/MODEL - 2011 Peterbilt 367 ENGINE/MODEL/SERL C15 SDP20462

1XPTDB0XXBD119128

TRNS/MODEL/SERL - RTL018918B S0812797

RXLS MODEL/SERL - D46-170 HN03472579 D46-170 HN03472580 ENG HRS 14306.0

SELL DLR

ENGHRS - 14306.0 MEMO

PTO

COMPLETE 08-30-18

CPL/ARRG P011

DEL DATE 07-19-10 DEL MILE 2209

INSPECT CAUSE OF OIL CONTAMINATION.

CAUSE:

COOLANT CONTAMINATION IN OIL.

CORRECTION:

DRAINED OIL AND REMOVED OIL PAN.

PRESSURE TEST COOLING SYSTEM AND INSPECT FOR LEAK-NOTHING DEFINATIVE-ADVISED CUSTOMER.

DRAINED COOLING SYSTEM AND STRIPPED ENGINE DOWN.

REMOVED HEAD AND LINERS. POSSIBLE HEAD CRACKED.

CLEANED ALL COMPONENTS FOR REUSE.

PLATNIUM KIT INFRAMED.

INSTALLED LINER PACKS AND MEASURED PROTRUSION-BLOCK HAD BEEN PREVIOUSLY CUT.REPLACED WATER PUMP AND REAR HOUSING-CORROSION-ROLL MAIN BEARING AND THRUSTS. TORQUE CAPS TO SPEC.

SECURE RODS TO CRANK. TORQUE CAPS TO SPEC.

INSTALLED REMAN OIL PUMP AND ASSEMBLE PLATE AND PICK UP TUBES.

CLEAN AND PAINT OIL PAN AND INSTALL.

ASSEMBLED REMAN HEAD AND INSTALLED. TORQUE CYLINDERHEAD TO SPEC.

ASSEMBLED EXTERNAL ENGINE COMPONENTS.SET GEAR TRAIN BACKLASH.

INSTALLED REMAN INJECTORS AND TORQUED TO HOLDOWN BOLTS TO SPEC.

ASSEMBLED OVERHEAD AND CARRIED OUT SET. CLOSED TOP OF ENGINE.

INSTALLED ENGINE FLUID AND CHANGED ALL FILTERS. INSPECT AIR CLEANER

CANISTERS-OK-

PRIME FUEL SYSTEM AND RUN ENGINE.

TOPPED OFF FLUIDS AND ROAD TEST.

CONTINUED



Peterbilt Thunder Bay 1145 Commerce Street Thunder Bay, ON P7E 6E8 (807) 577-5793 (800) 465-5030 Fax (807) 577-8918

CUSTOMER NAME

THUNDER BAY TRUCK CENTRE, Inc. WWW.TBTC.CA

EMAIL: MAIL@TBTC.CA

Peterbilt Fort Frances 505 McIrvine Road Fort Frances, ON P9A 3X7 (888) 889-2344 (807) 274-7936 Fax (807) 274-2813

Peterbilt Dryden 70 Keith Avenue Dryden, ON P8N 3K8 (807) 223-7577 (844) 223-7577 Fax (807) 223-8482

PAGE 2 w

REPRINT CUSTOMER INVOICE

INVOICE DATE 09-13-18

REPAIR ORDER NUMBER >>>> DR8108 <<<<

NUMBER PHONE

TOTAL LABOR 5,850.00 TOTAL PARTS 20,515.11 TOTAL FREIGHT 25.00 TOTAL MHSW FEE 13.30

Qty	Part Number	Description	IIni t	Extended	
Qty Part Number Description Unit Extended 1 EB1CRSS CLEANER-ENGINE 454 G 6.70 6.70 3 D39054 3/8 X 1 NC GR 8 BOLT 0.18 0.54 3 39703 3/8 FLAT WASHER GR 8 SAE ZYT 0.05 0.15 14 313KLE BRK KLEEN 2.20 30.80 4 4795400 PAINT-YELLOW 17.74 70.96 1 20R7414 ENG KIT 18,045.00 18,045.00 1 350-0111 HEATER-BLOCK, ENGINE 79.80 79.80 2 2727018 SEAL 36.03 72.06 2 4795400 PAINT-YELLOW 17.74 35.48 2 39703 3/8 FLAT WASHER GR 8 SAE ZYT 0.05 0.10 1 90-0011TCP CLAMP-V BAND 2.5" 12.58 12.58					
1	EB1CRSS	CLEANER-ENGINE 454 G	6.70	6.70	
3	D39054	3/8 X 1 NC GR 8 BOLT	0.18	0.54	
3	39703	3/8 FLAT WASHER GR 8 SAE ZYT	0.05	0.15	
14	313KLE	BRK KLEEN	2.20	30.80	
4	4795400	PAINT-YELLOW	17.74	70.96	
1	20R7414	ENG KIT	18,045,00	18.045.00	
1	350-0111	HEATER-BLOCK, ENGINE	79.80	79.80	
2	2727018	SEAL	36.03	72.06	
2	4795400	PAINT-YELLOW	17.74	35.48	
2	39703	3/8 FLAT WASHER GR 8 SAE ZYT	0.05	0.10	
1.	90-0011TCP	CLAMP-V BAND 2.5"	12.58	12.58	
1	2412634	CLAMP AS-	22.81	22.81	
1.	35337	2.5" U CLAMP	3.74	3.74	
1	CGIPLUG	PLUG	130.92	130.92	
2	CM3999	CLAMP-HOSE 5/16X7/8 SS/CS	1.14	2.28	
2	RS5288XPJAB	AIR FILTER	87.34	174.68	
1	2862969	ELBOW-WAT	1,300.99	1,300.99	
7	D1030-2650	HOSE-RADIATOR #40 1 PICK=	2.00	14.00	
1	2954463	HOSE-PREOOLE	50.44	50.44	
2	9216TRP	CLAMP-HOSE W/LINER #16	1.78	3.56	
1	360-0008	CORD-72"-120V 16-3HPN TRK	29.39	29.39	
1	HE8716	HOSE-HUMP DBL 4"X6" SILTU	37.72	37.72	
1	HE8716	HOSE-HUMP DBL 4"X6" SILTU	37.72	37.72	
3	D1030-2364	HOSE-RADIATOR #20 J20R1-A	1.83	5.49	
11	EC7501	COOLANT-TRP ELC 50/50 JUG	10.50	115.50	
1	2568753	FILTER AS SE	32.00	32.00	
1	6V6353	SEAL O RING	30.18	30.18	
2	12	SHRINK TERMINALS	1.60	3.20	
42	15W40	15W40 ENGINE OIL	3.96	166.32	
1	FREIGHT		25.00	25.00	
1	EB1CRSS&	F.E.T.	0.17	0.17	
14	313KLE&	F.E.T.	0.23	3.22	
4	4795400&	F.E.T.	0.06	0.24	
2	4795400&	F.E.T.	0.06	0.12	
11	EC7501&	F.E.T.	0.76	8.36	
1,	2568753&	3/8 X 1 NC GR 8 BOLT 3/8 FLAT WASHER GR 8 SAE ZYT BRK KLEEN PAINT-YELLOW ENG KIT HEATER-BLOCK, ENGINE SEAL PAINT-YELLOW 3/8 FLAT WASHER GR 8 SAE ZYT CLAMP-V BAND 2.5" CLAMP AS- 2.5" U CLAMP PLUG CLAMP-HOSE 5/16X7/8 SS/CS AIR FILTER ELBOW-WAT HOSE-RADIATOR #40 1 PICK= HOSE-PREOOLE CLAMP-HOSE W/LINER #16 CORD-72"-120V 16-3HPN TRK HOSE-HUMP DBL 4"X6" SILTU HOSE-HUMP DBL 4"X6" SILTU HOSE-RADIATOR #20 J20R1-A COOLANT-TRP ELC 50/50 JUG FILTER AS SE SEAL O RING SHRINK TERMINALS 15W40 ENGINE OIL F.E.T. F.E.T. F.E.T. F.E.T. F.E.T. F.E.T. F.E.T. F.E.T. F.E.T.	1.19	1.19	

CONTINUED

AUTHORIZED DEALER FOR CUMMINS & CATERPILLAR ENGINES



THUNDER BAY TRUCK CENTRE, Inc. WWW.TBTC.CA EMAIL: MAIL@TBTC.CA

oo mana

Peterbilt Thunder Bay 1145 Commerce Street Thunder Bay, ON P7E 6E8 (807) 577-5793 (800) 465-5030 Fax (807) 577-8918

CUSTOMER NAME

Peterbilt Fort Frances 505 McIrvine Road Fort Frances, ON P9A 3X7 (888) 889-2344 (807) 274-7936 Fax (807) 274-2813 Peterbilt Dryden 70 Keith Avenue Dryden, ON P8N 3K8 (807) 223-7577 (844) 223-7577 Fax (807) 223-8482 REPRINT CUSTOMER INVOICE PAGE 3

*
INVOICE DATE 09-13-18

REPAIR ORDER NUMBER >>>> DR8108 <<<<

NUMBER PHONE

2 REPLACE OIL COOLER AS REQUIRED.

CAUSE:

REQUIRED.

CORRECTION:

REMOVED OIL COOLER ASSEMBLY-BADLY RUSTED/SEIZED BOLTS-CHANGED TUBES THAT TRANSFER COOLANT TO CGI COOLER. INSTALLED NEW COOLER, SEALS AND O RINGS.

 TOTAL LABOR
 325.00

 TOTAL PARTS
 1,443.52

 TOTAL FREIGHT
 300.00

Qty	Part Number	Description	Unit	Extended
1 1 1 1 1	6V5134 2722462 2642468 2642469 2655207 10R5676 2627221 2627221 FREIGHT	SEAL O RING SEAL SEAL-INTEGRA SEAL-INTEGRA SEAL CORE AS OIL TUBE TUBE	16.98 26.13 9.41 26.43 44.25 1,056.26 80.43 80.43 300.00	67.92 78.39 9.41 26.43 44.25 1,056.26 80.43 80.43 300.00
		MISCELLANEOUS S	UPPLY 315.	0.0

INV-ENVIRONMENTAL	13.30
SLS-SVC CUST LBR TRK	6,175.00
SLS-SUNDRIES	315.00
SLS-PTS SHOP	21,958.63
FREIGHT-PTS	325.00
H.S.T. R105278493	3,742.30
PLEASE PAY THIS TOTAL	32,529.23

IF YOUR WHEELS HAVE BEEN TORQUED, THEY MUST BE RETORQUED WITHIN 150 KM

Received By _____ Date ____

WARRANTY SUBJECT TO MANUFACTURER'S APPROVAL.
REJECTED CLAIMS ARE CUSTOMER'S RESPONSIBILITY.

AUTHORIZED DEALER FOR CUMMINS & CATERPILLAR ENGINES

Vehicle History Report #: 48484251
Report Date: September 15, 2023 | 9:51 AM EDT
Report Status: Complete
Reference: 2023 0 A02-2

2011 PETERBILT 367

Tractor truck | 6 Cylinders | Diesel 1XPTDB0XXBD119128
Country of Assembly: United States
Last Reported Odometer: 850,508 KM



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



2 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 15, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report



Accident/Damage





Registration

This vehicle has been registered in the province of Ontario in Canada with Normal branding.
We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS	
2018 Jan 25	683,828 KM	Kenora Truck Service Ltd. Mississauga, Ontario, Canada	Vehicle serviced	
2020 Feb 25	850,508 KM	Kenora Truck Service Ltd. Mississauga, Ontario, Canada	Vehicle serviced • Emission system checked	



Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact PETERBILT.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Jan 25	683,828 KM	Kenora Truck Service Ltd. Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2020 Feb 25	850,508 KM	Kenora Truck Service Ltd. Mississauga, Ontario, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

particular purpose registrining this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© 2023 CARFAX Canada ULC. All rights reserved.









CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:		Truck		Seatin	g Cap	acity:					
GVW:		kg		Brake	Brake Type:		Air			٠	
Owner Name:		RAM ENTERPR	ISES LTE								
Address:	(191	LARAVISTA DR	NE								
City:	CA	LGARY	Pro	vince:	AB			Post	al Code:	T3J	5B1
Telephone	Num	ber: (403) 45	9-9990	****							
Vehicle Identification Number: 1XPTDB0XBD119128											
Make:		PETERBILT		*		Model:	367				
Year:		2011				Unit Nu	mber:				
Odometer:		917911 KM	Licence	Plate Nu	ımber	: [Province	e:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:			Facility Number:		
Profix Truck Repair Itd.	21367				
Inspection Technician Name:			Technician Number:		
Harpreet Sidhu			C9978		
Inspection Technician Signature:		Jaz	ि सिंप		
Inspection Date:	2024/10/07		7		