



Brown's Industrial Sales
 Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 91-041

Branch		
COLD LAKE		*REPRINT*
Date	Time	Page
08/18/16	07:01:50 (B)	01
Account No	Phone No	Inv No
INT01		W02827
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson
		102

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
R0000382	2012 CENTERLINE 31		X 2C9DS3533CC181540		
91-041	31" END DUMP	193801			

REPAIR# 1 C COO02 N/A 08/04/16 08/04/16

Air Bag blown

COMPLAINT:

RH axle lift air bag leaking air between billows

CORRECTION:

(04/08/16-BOB.JR) REMOVED OLD LIFT BAG AND ORDERED NEW ONE. SHOULD BE HERE TOMORROW. PLUGGED OFF AIR LINE AND ZIP TIED IT TO UNIT. WAITING ON BAG. BAG ARRIVED INSTALLED ON TRAILER AND TESTED WORKS.

W01-358-6902	air bag	RETAIL	156.00		
		1 N	135.00	135.00	
440761	3/8 AR BRK BRAS	RETAIL	6.19		
		1	5.16	5.16	
	3/8 AR BRK BRASS UNION				
5126701	3/8X1/4 MPT CON	RETAIL	3.02		
		1	2.52	2.52	
69836	BR PIPE COUPLIN	RETAIL	1.49		
		1	1.24	1.24	
80090	3/8" FUEL LINE	RETAIL	5.28		
		1	4.40	4.40	
	BY THE FOOT				
		PARTS		148.32	
		LABOR		187.50	
50210501		REPAIR TOTAL==>		335.82	

REPAIR# 2 C COO02 OVRMTT 08/04/16 08/04/16

ON VEHICLE: Repair Medium Truck Tire .50 HRS

COMPLAINT:

RH front axle outer tire is very bad and has cords visible.

CONTINUED ON PAGE 02

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Brown's Industrial Sales

Highway 16 W & Range Road 20

P.O. Box 21092 Lloyd Mall

Lloydminster, AB T9V 2S1

780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:

63214 Highway 892 • P.O. Box 1267

Cold Lake, AB T9M 1P3

780-826-2399 • Fax: 780-826-2390

Ship To: SAME AS BELOW

Invoice To: 91-041

Branch COLD LAKE		
Date 08/18/16	Time 07:01:50 (B)	Page 02
Account No INT01	Phone No	Inv No W02827
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson 102

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
R0000382	2012 CENTERLINE 31		X 2C9DS3533CC181540		
91-041	31" END DUMP	193801			

CORRECTION:

(04/08/16-BOB.JR) LIFTED UNINT UP REMOVED WHEEL FROM UNIT. DEFLATED IT AND REMOVED TIRE FROM RIM. CHECKED RIM OVER FOR ANY CRACKS AND DAMAGED DONE TO IT. CLEANED UP RIM, REPLACED VALVE AND MOUNTED NEW TIRE TO RIM. AIRED UP IN TIRE CAGE. CHECKED FOR LEAKS. ALL GOOD. REINSTALLED ON TO UNIT

RS545D	545 ALCOA VALVE	RETAIL	3.10		
		1	2.58		2.58
TDS	TIRE TAX	1	9.00		9.00
	TIRE DISPOSAL SURCHARGE				
1133991456	11R24.5	RETAIL	324.74		
		1	270.62		270.62
			PARTS		282.20
			LABOR		62.50
	50210501	REPAIR TOTAL==>			344.70

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	430.52	
LABOR	250.00	
SHOP SUPPLIES	24.43	
INTERNAL TOTAL	704.95	

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By