



Brown's Industrial Sales
 Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 55-038

Branch		
COLD LAKE		*REPRINT*
Date	Time	Page
01/23/26	07:08:17 (B)	01
Account No	Phone No	Inv No
INT01		W16490
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson
		100

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
000654	55-038	EZ38-MX-TRK	X WNCE0702APAL01064	
55-038	EZ38			

SEGMENT# 1 C GAU01 * 12/29/25 12/29/25

RENTAL RETURN INSPECTION

CORRECTION:

DEC 29/25 R.G

WENT THROUGH MACHINE FOLLOWING INSPECTION/SERVICE CHECKLIST. ALL FLUIDS WERE CHECKED, WASHER FLUID TOPPED UP AND SOME COOLANT REMOVED AS IT WAS OVER FULL. VACUMED MACHINE OUT.

- MISSING TWO HVAC VENTS. (PARTS ORDERED).
 - HOSE ON BOOM WAS LEAKING (TIGHTENED FITTING).
 - HORN BUTTON MISSING (PARTS ORDERED).
 - WASHER FLUID NOT WORKING. DISCONNECTED AND TESTED POWER WIRES, GETTING 12.7 VOLTS. CONNECTED AND HAD SEAN RUN WASHER TO SEE IF I CAN HEAR MOTOR WORKING AND ITS NOT. (PARTS ORDERED).
 - INTERIOR LIGHT BURNT OUT. (REPLACED).
 - REAR WORK LIGHT BURNT OUT. (REPLACED WITH NEW LIGHT AND WEATHERPACK CONNECTORS).
- JAN 09/26 R.G
- TOOK APART JOYSTICK CONSOLE TO GET HORN BUTTON OUT. WIRING RUNS THROUGH ALL THE WAY TO THE BOTTOM OF ARMREST AND I CANT PULL WIRING THROUGH. SPLICED NEW HORN BUTTON TO EXISTING HARNESS AND TESTED THAT IT WORKS.
 - REMOVED OLD WASHER PUMP AND INSTALLED NEW. TESTED BUT THE LINE WAS PLUGGED ON THE NOZZLE END. BLEW OUT AND REINSTALLED. WORKS NOW.
 - REMOVED VENT LOUVERS AND INSTALLED NEW.

BZ201-5	SQUARE LED LIGH	RETAIL	59.38	
		1 T	45.68	45.68

CONTINUED ON PAGE 02

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Brown's Industrial Sales
 Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 55-038

Branch		
COLD LAKE		
Date	Time	Page
01/23/26	07:08:17 (B)	02
Account No	Phone No	Inv No
INT01		W16490
Ship Via	Purchase Order	
Tax Exempt ID No.		
		Salesperson
		100

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
000654	55-038	EZ38-MX-TRK	X WNCE0702APAL01064	
55-038	EZ38			
1000125144		pump washtank	RETAIL	34.13
			1 T	19.92
				19.92
1000234571		retrofit kit fe	RETAIL	160.03
			1 T	93.46
				93.46
1000264494		round nozzle	RETAIL	38.85
			2 T	36.39
				72.78
124557		EP102 GREASE	RETAIL	7.97
			2 T	6.13
				12.26
15-215		WINTER WASHER F	RETAIL	5.85
			1 T	4.48
				4.48
		WINDSHIELD WASHER FLUID -35 C		
4PTAG		YELLOW FE TAG	RETAIL	1.30
			1 T	1.00
				1.00
6418		BULB	RETAIL	2.31
			1 T	1.78
				1.78
			PARTS	251.36
			LABOR	765.40
	50210501		SEGMENT TOTAL==>	1016.76

SEGMENT# 2 C CAL01 * 12/29/25 12/29/25

ignition issues

CORRECTION:

JAN 09/26 C.B, CHECKED THE PROBLEM WITH THE IGNITION, THE KEY IS NOT GOING INTO THE START POSITION, NOT SPRING ON THE SWITCH WHEN TURNING IT, TOOK THE IGNITION SWITCH A PART AND THING INSIDE FELL OUT, SPRING AND THINGS, PUT IT BACK TOGETHER A NUMBER OF TIMES BEFORE I FIGURED OUT HOW IT WENT BACK TOGETHER, TESTED THE SWITCH AND IT IS SPRINGING WENT IN THE START POSITION AND THE UNIT STARTS, TRIED IT A NUMBER OF TIMES AND WORKED EVERY TIME.

CONTINUED ON PAGE 03

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.

I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By



Brown's Industrial Sales

Highway 16 W & Range Road 20
 P.O. Box 21092 Lloyd Mall
 Lloydminster, AB T9V 2S1
 780-875-2339 • Fax: 780-875-0262

PLEASE REMIT TO:
 63214 Highway 892 • P.O. Box 1267
 Cold Lake, AB T9M 1P3
 780-826-2399 • Fax: 780-826-2390

Ship To: Same as Below

Invoice To: 55-038

Branch COLD LAKE		
Date 01/23/26	Time 07:08:17 (B)	Page 03
Account No INT01	Phone No	Inv No W16490
Ship Via	Purchase Order	
Tax Exempt ID No.		
	Salesperson 100	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
000654	55-038	EZ38-MX-TRK	X WNCE0702APAL01064	
55-038	EZ38			
	50210501			
			LABOR	642.60
			SEGMENT TOTAL==>	642.60

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	251.36	
LABOR	1408.00	
INTERNAL TOTAL	1659.36	

TERMS AND CONDITIONS

I request the above work to be done and the above materials to be supplied and installed on the following conditions.
 I promise to pay the amount due upon completion of the work. I acknowledge the lien of the operator for the value of the work and materials supplied. I authorize you, your agents, or independent contractors to drive my vehicle for the purpose of inspection and repairs. I authorize you to subcontract work as necessary, including releasing the vehicle or parts thereof to third parties. I will be responsible for any and all charges that any third party warranty company fails to pay for.

X

Authorized By